



VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT. FOR REPAIR DETAILS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

## NOTES

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE BASED ON THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ENTER THE ACTUAL QUANTITIES INTO THE AS-BUILT REPAIR QUANTITY TABLE.

CONCRETE REPAIRS MAY BE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

FOR SHOTCRETE REPAIR, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIR, SEE SPECIAL PROVISIONS.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

CLEAN AND REMOVE DEBRIS FROM THE TOP OF THE CAP. EPOXY COATING SHALL BE APPLIED TO THE TOP SURFACE OF THE CAP. THE CONTRACTOR SHALL NOT COAT THE AREA OF THE CAP BENEATH THE MASONRY PLATES. FOR EPOXY COATING, SEE SPECIAL PROVISIONS.

CONCRETE REPAIR AREA

SHOTCRETE REPAIR AREA

---- EPOXY RESIN INJECTION (ERI)

PROJECT NO. I-5746C

MECKLENBURG COUNTY

BRIDGE NO.: 590328

SHEET 2 OF 2

DocuSigned by:

02EE938FAB674C5...

OZEE938FAB674C5...

OZEE938FAB

STATE OF NORTH CAROLINA

DEPARTMENT OF TRANSPORTATION

RALEIGH

END BENT 2

8/23/2021

SOUTHBOUND

REVISIONSSHEET NODOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETEDNo.BY:DATE:No.BY:DATE:S8-2013TOTAL SHEETS24274

DATE : <u>05/2021</u>

R.L.PUTEK

H. A. LOCKLEAR

DRAWN BY : \_

CHECKED BY : .