

AS-BUILT REPAIR QUANTITY TABLE LINDERSTDE OF DECK REPATRS

	ONDERSIDE OF	DECK	DECK REPAIRS			
UNDERSIDE OF DECK O.O OVERHANG DIAPHRAGMS O.O UNDERSIDE OF OVERHANG INTERIOR DIAPHRAGMS O.O ESTIMATE UNDERSIDE EPOXY RESIN INJECTION O.O LIN.FT.		ESTIMATE		ACTUAL		
OVERHANG DIAPHRAGMS UNDERSIDE OF OVERHANG INTERIOR DIAPHRAGMS O.O ESTIMATE UNDERSIDE EPOXY RESIN INJECTION O.O LIN.FT.	SHOICRETE REPAIRS			AREA SQ.FT.	VOLUME CU. FT.	
UNDERSIDE OF OVERHANG INTERIOR DIAPHRAGMS O.O ESTIMATE UNDERSIDE EPOXY RESIN INJECTION O.O LIN.FT.	UNDERSIDE OF DECK	0.0	0.0			
INTERIOR DIAPHRAGMS O.O O.O ESTIMATE UNDERSIDE EPOXY RESIN INJECTION O.O LIN.FT.	OVERHANG DIAPHRAGMS	0.0	0.0			
UNDERSIDE EPOXY RESIN INJECTION O.O LIN.FT.	UNDERSIDE OF OVERHANG	0.0	0.0			
UNDERSIDE EPOXY RESIN INJECTION 0.0 LIN.FT.	INTERIOR DIAPHRAGMS	0.0	0.0			
				ACTUAL		
UNDERSIDE EPOXY COATING O SQ.FT.	UNDERSIDE EPOXY RESIN INJECTION					
	UNDERSIDE EPOXY COATING	O SQ.FT.				

UNDERSIDE OF DECK REPAIR QUANTITIES REPRESENT ESTIMATED VALUES OF DECK REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM OF 2"CLEAR TO SAWCUT. SEE REPAIR DETAILS.

NOTES

FOR BEAM REPAIR DETAILS, SEE "BEAM SECTION REPAIR DETAILS" SHEET.

FOR BEAM PLATING REPAIR, SEE "BEAM PLATING REPAIR DETAILS" SHEET.

FOR BRIDGE JACKING DETAILS, SEE "JACKING DETAILS" SHEET.

FOR UNDERSIDE OF DECK AND OVERHANG REPAIRS, SEE "OVERHANG, DIAPHRAGM AND BRIDGE RAIL REPAIR DETAILS" SHEET.

THE LOCATIONS AND DIMENSIONS OF THE AREAS FOR REPAIR ARE BASED ON THE BEST INFORMATION AVAILABLE. THE CONTRACTOR, IN CONJUNCTION WITH THE ENGINEER, SHALL VERIFY THE LOCATION AND EXTENT OF REPAIR AREAS PRIOR TO STEEL FABRICATION.

UNDERSIDE EPOXY COATING

UNDERSIDE REPAIR

‱ DIAPHRAGM REPAIR

- BEAM NUMBER
- BEAM END REPAIR
- (P) PLATING REPAIR
- S STIFFENER REPAIR
- D STEEL DIAPHRAGM REPAIR

PROJECT NO. I-5746C MECKLENBURG COUNTY BRIDGE NO. 590332

SHEET 6 OF 11

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION

DECK UNDERSIDE REPAIR SPAN L & M

SEAL 35647 8/23/2021 **REVISIONS**

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

DocuSigned by:
02EE938FAB674C5...

DIM "D"

DIM "C"

ANTICIPATED BEAM REPAIR LOCATIONS

DIM "B"

DIM "A"

LOCATION

BENT 10

SPAN | BEAM

13

SHEET NO NO. BY: DATE: S10-22 DATE: TOTAL SHEETS 274

R.L.PUTEK/E.BAYISSA _ DATE : <u>07/2021</u> DRAWN BY : ___ DATE : 07/2021 H. A. LOCKLEAR CHECKED BY : _

PLAN