

DRAWN BY : .	R.L.PUTEK	DATE : <u>06/2021</u>	
CHECKED BY	H.A. LOCKLEAR	DATE : <u>06/2021</u>	
		23-110-2021 12:03	

+

+



REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE BASED ON THE BEST

AS-BUILT REPAIR QUANTITY TABLE						
DENIT 3	QUANTITIES					
BENT 3	ESTIMATE		ACTUAL			
SHOTCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.		
САР	111.6	55.8				
COLUMNS	28.6	14.3				
CONCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.		
САР	57.7	28.9				
EPOXY RESIN INJECT	LIN.FT		LIN.FT			
САР	11.0					
COLUMNS		0.0				
EPOXY COATING	SQ.FT.		SQ.FT.			
TOP OF BENT CAP	239					

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND 2" MIN. CLEAR TO SAWCUT. FOR REPAIR DETAILS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

SPAN D SPAN C

PROJECT NO. \_\_\_\_\_\_\_ MECKLENBURG COUNTY BRIDGE NO. 590332 SHEET 1 OF 4 DocuSigned by: STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION WINTH CARO RALEIGH T AN OFESSION SEAL 35647 BENT 3 OAM A. SPAN C FACE 8/23/2021 SHEET NO REVISIONS NO. DATE: S10-39 DATE: BY: BY: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED total sheets 274