

+

+

NOTES



	AS-BUILT REPA	TR QI	JANTTI	ΓΥ ΤΔ	BLF	
	BENT 3 QUANTITIES					
	SHOTCRETE REPAIRS	ESTI AREA	VOLUME	ACT AREA	VOLUME	
	CAP	SQ.FT. 4.9	CU.FT. 2.5	SQ.FT.	CU.FT.	
	COLUMNS	35.4	17.7			
	CONCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.	
	САР	6.9	3.5			
	EPOXY RESIN INJECT	LIN.FT		LIN.FT		
	CAP COLUMNS	25 . 0 0 . 0				
	EPOXY COATING		SQ. FT.		SQ.FT.	
	TOP OF BENT CAP 251 VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER					
	REMOVAL OF UNSOUND CONCRETE, MIN. OF 1" BEHIND REBAR AND 2" MIN. CLEAR TO SAWCUT. FOR REPAIR DETAILS, SEE "TYPICAL CAR AND COLUMN REPAIR DETAILS" SHEET					
	CAP AND COLUMN REPAIR DETAILS"SHEET.					
_						
<u>)</u> C						
SPAN C SPAN D						
∕—1.5 LF ERI						
	}					
	4.2 SF SHOTCRETE REPAIR					
	PROJECT NO. <u>I-5746C</u>					
	MECKLENBURG COUNTY					
	BRIDGE NO. 590332					
_	END VIEW DocuSigned by: SHEET 2 OF 4					
	DEPARTMENT OF TRANSPORTATION					
	RALEIGH					
	BENT 3					
	BENT 3 SPAN A. COLUMN 8/23/2021 BENT 3 SPAN C FACE					
	8/23/2021	_	-			
			EVISIONS		SHEET NO.	
ſ	FINAL UNLESS ALL	BY: DATE:	3	DATE:	S10-40 TOTAL SHEETS	
	SIGNATURES COMPLETED 🙎		4		274	