

23-AUG-2021 12:03 R:\Structures\FINAL PLANS\Bridge 332\410\_081\_I5746C\_SMU\_B3D\_S10-41\_590332.dgn aacole

+

AS-BUILT REPAIR QUANTITY TABLE				
BENT 3	QUANTITIES			
	ESTIMATE		ACTUAL	
SHOTCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.
САР	33.6	16.8		
COLUMNS	23.2	11.6		
CONCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.
САР	0.0	0.0		
EPOXY RESIN INJECTION		LIN.FT		LIN.FT
САР		9 <b>.</b> 5		
COLUMNS		0.0		
EPOXY COATING		SQ.FT.		SQ.FT.
TOP OF BENT CAP		0		
VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER				

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1" BEHIND REBAR AND 2" MIN. CLEAR TO SAWCUT. FOR REPAIR DETAILS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

SPAN D SPAN C

	PROJECT NO. <u>I-5746C</u> <u>MECKLENBURG</u> county BRIDGE NO. <u>590332</u>			
SHEET 3 OF 4				
DocuSigned by:				
SEAL 35647 MANNELR SEAL 35647 MANNELR COLUMN	BENT 3 SPAN D FACE			
8/23/2021				
	REVISIONS SHEET NO.			
DOCUMENT NOT CONSIDERED FINAL UNLESS ALL	1 3 TOTAL SHEETS			
SIGNATURES COMPLETED	2 4 274			