

+

+

					1 1	1
					1 1	1
					1 1	
					1 1	1
					1 1	1
					1 1	1

AS-BUILT REPA	IR QU	IANTI	ΓΥ ΤΑ	BLE		
BENT 3	QUANTITIES					
	ESTI			UAL		
SHOTCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.		
САР	78.7	39.4				
COLUMNS	4.7	2.4				
CONCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.		
САР	0.0	0.0				
EPOXY RESIN INJECT	EPOXY RESIN INJECTION					
САР	САР					
COLUMNS	COLUMNS					
EPOXY COATING	EPOXY COATING					
TOP OF BENT CAP	TOP OF BENT CAP					
VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND 2" MIN. CLEAR TO SAWCUT. FOR REPAIR DETAILS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET. SPAN D SPAN C						
SPAN D SPAN C						

RETE R		
E		
		PROJECT NO. <u>I-5746C</u> <u>MECKLENBURG</u> COUNTY
	END VIEW	BRIDGE NO. 590332
	D2EE938FAB674C5	STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH
	SEAL 35647 ************************************	BENT 3 SPAN D FACE
	8/23/2021	SFAN D FACE
		REVISIONS SHEET NO. NO. BY: DATE: NO. BY: DATE: S10-42
	DOCUMENT NOT CONSIDER FINAL UNLESS ALL SIGNATURES COMPLETED	1 TOTAL SHEETS