DocuSign Envelope ID: 21225878-B82E-477D-9D10-B62A1A8A1632

+


+

AS-BUILT REPAIR QUANT]	TY T	ABLE
	ESTIMATE	ACTUAL
TYPE-III STRUCTURE ANCHOR UNITS	4 E A	
GUARDRAIL REMOVAL	475 LF	
PROPOSED GUARDRAIL	400 LF	
INCIDENTAL MILLING	556 SY	
ASPHALT CONCRETE SURFACE COURSE, TYPE SF9.5C	50 TON	



1.	INCIDENTAL MILLING -
1.0	NECESSARY TO ATTAIN
	PAVEMENT SHALL BE OF
	BETWEEN THE ROADWAY
	MAY EXCEED $1^{1/2}$ due to





8/25/2021 I5939_SMU_AR01_770104.dgn fflores