



AS-BUILT REPAIR QUANTITY TABLE

SLOPE PROTECTION REPAIRS	QUANTITIES			
	ESTIMATE		ACTUAL	
SLOPE PROTECTION VOID FILLING	500	LBS.		
SILICONE JOINT SEALANT FOR SLOPE REPAIRS	87	LF		



SECTION ALONG END BENT
(EXISTING SLOPE)




SECTION ALONG END BENT
(PROPOSED SLOPE REPAIR)

NOTES:

1. AFTER COMPLETION OF VOID FILLING, SEAL CRACKS IDENTIFIED WITH POURABLE SILICONE JOINT SEALANT AS DESCRIBED IN THE SPECIAL PROVISIONS FOR SILICONE JOINT SEALANT FOR SLOPE REPAIRS (BACKER RODS MAY BE OMITTED AS APPROVED BY THE ENGINEER)
2. FOR SLOPE PROTECTION VOID FILLING/ SILICONE JOINT SEAL LOCATIONS SEE, "GENERAL DRAWING" SHEET
3. FOR SLOPE PROTECTION VOID FILLING, SEE SPECIAL PROVISIONS
4. FOR SILICONE JOINT SEALANT FOR SLOPE PROTECTION REPAIR, SEE SPECIAL PROVISIONS
5. FOR SILICONE JOINT SEALANT FOR SLOPE PROTECTION REPAIR, SEE "JOINT SEAL REPAIR ELEVATION VIEW" DETAIL

PROJECT NO. I-5939
ROBESON COUNTY
 BRIDGE NO. 770131



STATE OF NORTH CAROLINA
 DEPARTMENT OF TRANSPORTATION
 RALEIGH

SLOPE PROTECTION REPAIRS

DRAWN BY : FIDEL L. FLORES DATE : 06/2021
 CHECKED BY : DIEGO A. AGUIRRE DATE : 06/2021
 DESIGN ENGINEER OF RECORD: JACOB H. DUKE DATE : 06/2021

DOCUMENT NOT CONSIDERED
 FINAL UNLESS ALL
 SIGNATURES COMPLETED

REVISIONS						SHEET NO.
NO.	BY:	DATE:	NO.	BY:	DATE:	TOTAL SHEETS
1			3			9
2			4			