STATE	\mathbb{OF}	N	OR'	TH	$\mathbb{C}\mathbb{A}$	ROL	IN	A
DIVI	SION	V	OF	HI	GHW	VAY	S	

FORSYTH COUNTY


SIAIB	SIA	IE PROJECI REFERENCE NO.	NO.	SHEETS
N.C.	1	5BPR.55	1A	
STATE	PROJ. NO.	F. A. PROJ. NO.	DESCRIPT	NOI
15BI	PR.55		P.E	•
15BI	PR.55		CONST.	


LOCATION: BRIDGE No. 330078 ON US-52 /US-311 OVER US-311 /I-40

BRIDGE No. 330227 ON NC 67 OVER US421 BRIDGE No. 330392 ON SR 2643 OVER I-74 AND US311

INDEX OF STRUCTURES SHEETS

<u>DESCRIPTION</u>	STRUCTURE No. 330078		STRUCTURE No. 330227		STRUCTURE No. 330392	
TITLE SHEET INDEX OF SHEETS	SHEET No.	DESCRIPTION	SHEET No.	DESCRIPTION	SHEET No.	DESCRIPTION
LOCATION SKETCHES	S1-01	GENERAL DRAWING	S2-01	GENERAL DRAWING	S3-01	GENERAL DRAWING
TOTAL BILL OF MATERIALS	<i>S1–02</i>	GENERAL DRAWING	S 2-02	GENERAL DRAWING	S3-02	GENERAL DRAWING
	<i>S1–03</i>	TYPICAL SECTION	S2-03	TYPICAL SECTION	S 3–03	TYPICAL SECTION
		DECK SURFACE REPAIR	S2-04 THRU S	S2-08 DECK SURFACE REPAIR	S3-04 THRU S3-0	77 DECK SURFACE REPAIR
	<i>S1–08</i>	JOINT DETAILS	<i>S2-09</i>	JOINT DETAILS	<i>S3–08</i>	JOINT DETAILS
	<i>S1–09</i>	JOINT DETAILS	S2-10	JOINT DETAILS	<i>S3-09</i>	JOINT DETAILS
	S1-10 THRU S1-13	DECK UNDERSIDE REPAIR	S2-11 THRU S	2–15 DECK UNDERSIDE REPAIR	S3-10 THRU S3-1.	3 DECK UNDERSIDE REPAIR
	<i>S1–14</i>	END BENT 1	S 2–16	END BENT 1	<i>S3–14</i>	END BENT 1
	S1-15 THRU S1-16	BENT 1	S2-17 THRU S	S2-18 BENT 1	S3-15 THRU S3-1	6 BENT 1
	S1–17 THRU S1–18	BENT 2	S2–19 THRU S	S2-20 BENT 2	S3-17 THRU S3-1	8 BENT 2
	S1-19 THRU S1-20	BENT 3	S2-21 THRU S	2–22 BENT 3	S3-19 THRU S3-2	0 BENT 3
	<i>S1–21</i>	END BENT 2	S2-23 THRU S	S2-24 BENT 4	S3-21	END BENT 2
<u>DESCRIPTION</u>			S 2–25	END BENT 2		
	INDEX OF SHEETS LOCATION SKETCHES TOTAL BILL OF MATERIALS	TITLE SHEET INDEX OF SHEETS LOCATION SKETCHES TOTAL BILL OF MATERIALS \$1-01 \$1-02 \$1-03 \$1-04 THRU \$1-07 \$1-08 \$1-09 \$1-10 THRU \$1-13 \$1-14 \$1-15 THRU \$1-16 \$1-17 THRU \$1-18 \$1-19 THRU \$1-20 \$1-21	TITLE SHEET INDEX OF SHEETS LOCATION SKETCHES TOTAL BILL OF MATERIALS SI-02 SI-03 SI-04 THRU SI-07 DECK SURFACE REPAIR SI-08 SI-09 JOINT DETAILS SI-09 JOINT DETAILS SI-10 THRU SI-13 DECK UNDERSIDE REPAIR SI-14 END BENT 1 SI-15 THRU SI-16 BENT 1 SI-17 THRU SI-18 BENT 2 SI-19 THRU SI-20 BENT 3 SI-21 END BENT 2	TITLE SHEET SHEET O. DESCRIPTION SHEET No. INDEX OF SHEETS LOCATION SKETCHES S1-01 GENERAL DRAWING S2-01 TOTAL BILL OF MATERIALS S1-02 GENERAL DRAWING S2-02 S1-03 TYPICAL SECTION S2-03 S1-04 THRU S1-07 DECK SURFACE REPAIR S2-04 THRU S1-08 S1-08 JOINT DETAILS S2-09 S1-09 JOINT DETAILS S2-10 S1-10 THRU S1-13 DECK UNDERSIDE REPAIR S2-11 THRU S1-14 END BENT 1 S2-16 S1-15 THRU S1-16 BENT 1 S2-16 S1-17 THRU S1-18 BENT 2 S2-19 THRU S1-19 THRU S1-19 BENT 3 S1-19 THRU S1-20 BENT 3 S2-21 THRU S1-21 THRU S1-21 THRU S1-21 END BENT 2 S2-23 THRU S1-21 END BENT 3 S2-24 THRU S1-21 END BENT 3 S2-24 THRU S1-21 END BENT 3 S2-24 THRU S1-24 END BENT 3 S2-24 THRU S1-24 END BEN	TITLE SHEET SHEET No. DESCRIPTION SHEET No. DESCRIPTION	TITLE SHEET SHEETS LOCATION SKETCHES TOTAL BILL OF MATERIALS S1-01 S1-03 S1-04 S1-07 DECK SURFACE REPAIR S1-08 S1-09 S1-09 S1-01 S1-04 S1-07 DECK SURFACE REPAIR S1-09 S1-09 S1-01 S1-04 S1-04 S1-05 S1-06 S1-07 S1-08 S1-09 S1-09 S1-09 S1-09 S1-09 S1-09 S1-10 S





TYPE OF WORK:

BRIDGE PRESERVATION: DECK REPAIR, LATEX MODIFIED CONCRETE-VERY EARLY STRENGTH (LMC-VES) OVERLAY, LATEX MODIFIED CONCRETE-EARLY STRENGTH (LMC-ES) OVERLAY, SILANE DECK TREATMENT, POURABLE SILICONE JOINT SEALANT, FOAM JOINT SEALS FOR PRESERVATION, STEEL BEAM REPAIR, REPAIRS TO PRESTRESSED CONCRETE GIRDERS, PAINTING EXISTING WEATHERING STEEL STRUCTURE, CLEANING AND PAINTING EXISTING BEARING WITH HRCSA, EPOXY COATING CONCRETE GIRDER ENDS, EPOXY COATING AND DEBRIS REMOVAL AND SUBSTRUCTURE REPAIR.

Prepared in the Office of:

DIVISION OF HIGHWAYS
STRUCTURES MANAGEMENT UNIT

STRUCTURES MANAGEMENT UNIT
1000 BIRCH RIDGE DR.
RALEIGH, N.C. 27610