


1/21/2022 R:\Structures\Plans\402_049_15BPR49_SMU_SBR_B2B_S2-25_910240.dgn napierce



] ق

12'-6³⁄4"



AS-BUILT	REPAIR	QUANTITY	TABLE	

REPAIRS	QUANTITIES					
BENT 2 - SPAN B	ESTIMATE		ACTUAL			
SHOTCRETE REPAIRS	AREA SF	VOLUME CF	AREA SF	VOLUME CF		
САР	0	0				
COLUMN	1.0	0.5				
STRUT	0	0				
CONCRETE REPAIRS	AREA SF	VOLUME CF	AREA SF	VOLUME CF		
САР	0	0				
COLUMN	0	0				
STRUT	0	0				
EPOXY COATING		AREA SF		AREA SF		
САР		76				
STRUT		36				

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1" BEHIND REBAR AND MIN. 1" CLEAR TO SAWCUT. SEE REPAIR DETAILS.

NOTES

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN BASED ON THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ENTER THE ACTUAL QUANTITIES INTO THE AS-BUILT REPAIR QUANTITY TABLE.

CLEAN AND REMOVE DEBRIS FROM THE TOP OF THE CAP AND APPLY EPOXY PROTECTIVE COATING. EPOXY COATING SHALL BE APPLIED TO THE TOP SURFACE OF THE CAP. THE CONTRACTOR SHALL NOT COAT THE AREA OF THE CAP BENEATH THE MASONRY PLATES. FOR EPOXY COATING, SEE SPECIAL PROVISIONS.

CONCRETE REPAIRS MAYBE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS.



SHOTCRETE REPAIR AREA



CONCRETE REPAIR AREA



AREA PREVIOUSLY ACCOUNTED FOR ON ADJACENT FACE

	PROJEC	T NO.	15	BPR.4	9	
		WAKE		CO	UNTY	
	BRIDGE	NO	93	10240		
	SHEET 4 OF	12				
STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH						
SUBSTRUCTURE REPAIRS						
DocuSigned by: Nicholas Pierce			SENT N B F			
15110B434D0B485 01/21/2022	REVISIONS SHEET NO.					
DOCUMENT NOT CONSIDERED	NO. BY:		NO. BY:	DATE:	S2-25	
FINAL UNLESS ALL SIGNATURES COMPLETED	1		3 4		total sheets 73	