

## AS-BUILT REPAIR QUANTITY TABLE **QUANTITIES** REPAIRS BENT 3 - SPAN C **ESTIMATE** ACTUAL AREA VOLUME VOLUME AREA SHOTCRETE REPAIRS SF 0 0 5.2 2.6 COLUMN 0 AREA VOLUME VOLUME AREA CONCRETE REPAIRS SF 6.0 3.0 COLUMN 0 0 AREA AREA EPOXY COATING 76

36

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1" BEHIND REBAR AND MIN. 1" CLEAR TO SAWCUT. SEE REPAIR DETAILS.

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN BASED ON THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ENTER THE ACTUAL QUANTITIES INTO THE AS-BUILT REPAIR QUANTITY TABLE.

CLEAN AND REMOVE DEBRIS FROM THE TOP OF THE CAP AND APPLY EPOXY PROTECTIVE COATING. EPOXY COATING SHALL BE APPLIED TO THE TOP SURFACE OF THE CAP. THE CONTRACTOR SHALL NOT COAT THE AREA OF THE CAP BENEATH THE MASONRY PLATES. FOR EPOXY COATING, SEE SPECIAL PROVISIONS.

CONCRETE REPAIRS MAYBE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS.

SHOTCRETE REPAIR AREA



CONCRETE REPAIR AREA

AREA PREVIOUSLY ACCOUNTED FOR ON ADJACENT FACE

Nicholas Pierce ----15110B434D0B485..

PROJECT NO. 15BPR.49 **WAKE** COUNTY 910240 BRIDGE NO. \_\_\_

SHEET 6 OF 12

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION

## SUBSTRUCTURE REPAIRS

BENT 3 SPAN C FACE

01/21/2022 SHEET NO. REVISIONS S2-27 NO. BY: DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED 73

1/21/2022 R:\Structures\Plans\402\_053\_15BPR49\_SMU\_SBR\_B3C\_S2-27\_910240.dgn