

AS-BUILT REPAIR QUANTITY TABLE								
BENT 2 SPAN C FACE	QUANTITIES							
	ESII	ΜΑΤΕ	ACTUAL					
SHOTCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.				
САР	0.0	0.0						
COLUMN	0.0	0.0						
CONCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.				
САР	0.0	0.0						
COLUMN	0.0	0.0						
EPOXY RESIN INJECTIO	LIN.FT.	LIN.FT.						
САР	1.0							
COLUMN	0.0							

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT. SEE ``TYPICAL CAP AND COLUMN REPAIR DETAILS'' SHEET SD-01.

NOTES

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN BASED ON THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ENTER THE ACTUAL QUANTITIES INTO THE AS-BUILT REPAIR QUANTITY TABLE.

SHOTCRETE REPAIRS MAYBE SUBSTITUTED IN LIEU OF CONCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

FOR "TYPICAL CAP AND COLUMN REPAIR DETAILS," SEE SHEET SD-01.

SHOTCRETE REPAIR AREA



TH CAR FESSIO

SEAL 031021

CONCRETE REPAIR AREA

ERI - EPOXY RESIN INJECTION

PROJECT NO.	<u>I-5831A</u>
MADIS	SON COUNTY
BRIDGE NO	560547

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH

BE	2	
SPAN	С	FACE

DocuSigned by: Amber Mile POLESALEREAD (84							
03791854276542484	REVISIONS				SHEET NO.		
DOCUMENT NOT CONSIDERED	N0.	BY:	DATE:	NO.	BY:	DATE:	S3-19
FINAL UNLESS ALL	1			3			TOTAL SHEETS
SIGNATURES COMPLETED	2			4			24