## NOTES:

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER, THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.


CONCRETE REPAIRS MAY BE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

	EXISTING		
CONCRETE REPAIR	J - JACKET		
SHOTCRETE REPAIR	E - ENCAPSULATION		

ERI EPOXY RESIN INJECTION P - PILE

REPAIR QUANTITY TABLE					
DENT 15	QUANTITIES				
BENT 15	ESTIMATE		ACTUAL		
SHOTCRETE REPAIR	AREA SF	VOLUME CF	AREA SF	VOLUME CF	
CAP (VERTICAL FACE)	0.0	0.0			
CAP (HORIZONTAL FACE)	0.0	0.0			
COLUMN	0.0	0.0			
CONCRETE REPAIR					
CAP (VERTICAL FACE)	0.0	0.0			
CAP (HORIZONTAL FACE)	0.0	0.0			
COLUMN	0.0	0.0			
EPOXY RESIN INJECTION		LF		LF	
CAP		0.0			
COLUMN		0.0			

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT. SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.



30'-6"

SPAN 15
SPAN 16

P1 P2 P3 P4 P5

BOTTOM OF CAP

 DRAWN BY :
 S. T. SANDOR
 DATE : 05/2021

 CHECKED BY :
 W. C. SMITH
 DATE : 06/2021

SEAL 26445

\*\*INTITUTE OF THE PROPERTY NEW YORKS AND THE PROPERTY NEW YORK AND THE PROPERTY NEW

STATE OF NORTH CAROLINA

DEPARTMENT OF TRANSPORTATION

RALEIGH

BRIDGE NO. 060028

SHEET 15 OF 48

SUBSTRUCTURE BENT 15 REPAIR

P. Korey. Newton

4FFE39D1431B407...
01/27/2022

DOCUMENT NOT CONSIDERED

FINAL UNLESS ALL

SIGNATURES COMPLETED

REVISIONS

BY: DATE: NO. BY: DATE: S3-33

TOTAL SHEETS

78