NOTES:

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER, THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

CONCRETE REPAIRS MAY BE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.


	EXISTING		
CONCRETE REPAIR	J - JACKET		

SHOTCRETE REPAIR E - ENCAPSULATION

ERI EPOXY RESIN INJECTION P - PILE

REPAIR QUANTITY TABLE						
DENT 07	QUANTITIES					
BENT 23	ESTIMATE		ACTUAL			
SHOTCRETE REPAIR	AREA SF	V	/OLUME CF	AREA SF	VOLUME CF	
CAP (VERTICAL FACE)	0.0		0.0			
CAP (HORIZONTAL FACE)	0.0		0.0			
COLUMN	0.0		0.0			
CONCRETE REPAIR						
CAP (VERTICAL FACE)	0.0	0.0				
CAP (HORIZONTAL FACE)	0.0		0.0			
COLUMN	0.0		0.0			
EPOXY RESIN INJECTION			LF		LF	
CAP			0.0			
COLUMN			0.0			

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT. SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.



30'-6"

SPAN 23
SPAN 24

P1 P2 P3 P4 P5

BOTTOM OF CAP

 DRAWN BY :
 S. T. SANDOR
 DATE :
 05/2021

 CHECKED BY :
 W. C. SMITH
 DATE :
 06/2021

SEAL
26445

DocuSigned by:

P. Korey Newton

4FFE39D1431B407...
01/27/2022

PROJECT NO. 15BPR.56

BEAUFORT COUNTY

BRIDGE NO. 060028

SHEET 23 OF 48

STATE OF NORTH CAROLINA

DEPARTMENT OF TRANSPORTATION

RALEIGH

SUBSTRUCTURE
BENT 23 REPAIR

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED 2

REVISIONS

SHEET NO. BY: DATE: S3-41

TOTAL SHEETS
78