## NOTES: REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ENTER THE ACTUAL QUANTITIES INTO THE REPAIR QUANTITY TABLE. FOR ADDITIONAL NOTES, SEE SHEET 1 OF 5. 54'-0" - CONCRETE REPAIR AREA SPAN E SPAN D - SHOTCRETE REPAIR AREA 3.3 SF ─ 12.5 SF— 2.7 SF $\longrightarrow$ 3.2 SF -SEE — EAST FACE √1.3 SF 1.9 SF 1.0 SF — 1.6 SF — 1.0 SF 1.0 SF — 1.0 SF — **~** 1.0 SF 1.0 SF —

END VIEW

SPAN D SPAN E

REPAIR (	TAAUQ	ITY TA	BLE	
BENT 4	QUANTITIES			
	ESTIMATE		ACTUAL	
SHOTCRETE REPAIR	AREA S.F.	VOLUME C.F.	AREA S.F.	VOLUME C.F.
CAP (VERTICAL FACE)	53.5	26.8		
CAP (HORIZONTAL FACE)	0.0	0.0		
COLUMN AND STRUTS	3.0	1.5		
CONCRETE REPAIR				
CAP (VERTICAL FACE)	13.6	12.8		
CAP (HORIZONTAL FACE)	0.0	0.0		
COLUMN AND STRUTS	0.0	0.0		

SAWCUT. SEE REPAIR DETAILS.


6.2 SF (8" DEEP)

1.5 SF **\*\*\*\*\*\*** 

ELEVATION

EAST FACE (LOOKING WEST)

7.4 SF (14" DEEP)



PROJECT NO. 15BPR.47

\_\_\_ COUNTY

TOTAL SHEETS 31

EDGECOMBE

\_\_ DATE : <u>09/2021</u> \_\_ DATE : <u>02/2022</u>

ELEVATION

WEST FACE (LOOKING EAST)

PLAN BOTTOM OF CAP

END VIEW

NORTH FACE

DRAWN BY : \_

CHECKED BY :

A. Y. GODFREY

G. AYES