

AS-BUILT REPAIR QUANTITY TABLE

B	$\equiv$ NT 13	29		
CAP REPAIRS	ESTIMATE		ACTUAL	
SHOTCRETE REPAIRS	7.1 SF	3.6 CF	SF	Cf
EPOXY RESIN INJECTION	- LF			LF
COLUMN REPAIRS	ESTIMATE		ACTUAL	
SHOTCRETE REPAIRS	50.5 SF	25.3 CF	SF	CF
EPOXY RESIN INJECTION	4.3 LF		LF	
PILE REPAIRS	ESTIMATE		ACTUAL	
FRP PROTECTIVE SYSTEM AWL	- SF		SF	
ERP PROTECTIVE CYCTEM RWI	363 A SE		2	

FOR CAP REPAIRS: VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN.

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE

- FOR CONCRETE REPAIR DETAILS, SEE "TYPICAL CAP, COLUMN & UNDERDECK REPAIR DETAILS" & "PILE CONCRETE RESTORATION DETAILS" SHEETS.
- FOR FOOTING, COLUMN, AND STRUT REPAIR DETAILS, SEE "PILE FOOTING
- FOR PILE CONCRETE RESTORATION, SEE SPECIAL PROVISIONS.
- FOR FRP PROTECTIVE SYSTEM, SEE SPECIAL PROVISIONS.
- FOR FRP PROTECTIVE SYSTEM DETAILS AND UNDERWATER MORTAR REPAIRS, SEE "PILE FRP PROTECTIVE SYSTEM DETAILS" SHEET.

ERI - EPOXY RESIN INJECTION

- FRP PROTECTIVE SYSTEM

- SHOTCRETE REPAIRS

- PILE FOOTING RESTORATION

♠ FRP PROTECTIVE SYSTEM BELOW WATERLINE MAY INCLUDE APPROVED UNDERWATER MORTAR REPAIRS

HB-0017 DARE COUNTY 270009

STATE OF NORTH CAROLINA

RALEIGH

BENT 129

WEST FACE

SHEET NO REVISIONS NO. BY: DATE: TOTAL SHEETS