


+

+





AS-BUILT REPA	IR QU	JANTI	TY TA	BLE							
BENT 136											
CAP REPAIRS	ESTI	МАТЕ	ACTUAL								
SHOTCRETE REPAIRS	0.8 SF	0.4 CF	SF	CF							
EPOXY RESIN INJECTION	_	LF		LF							
COLUMN REPAIRS	ESTI	MATE	ACTUAL								
SHOTCRETE REPAIRS	46.0 SF	23.0 CF	SF	CF							
EPOXY RESIN INJECTION	5.3 LF		LF								
PILE REPAIRS	ESTI	MATE	ACTUAL								
FRP PROTECTIVE SYSTEM AWL	_	SF	SF								
FRP PROTECTIVE SYSTEM BWL		) SF	SF								

FOR CAP REPAIRS: VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS.

NOTES:

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIR DETAILS, SEE ``TYPICAL CAP, COLUMN & UNDERDECK REPAIR DETAILS''& ``PILE CONCRETE RESTORATION DETAILS'' SHEETS.

FOR FOOTING, COLUMN, AND STRUT REPAIR DETAILS, SEE ``PILE FOOTING RESTORATION' SHEET.


FOR PILE CONCRETE RESTORATION, SEE SPECIAL PROVISIONS.

FOR FRP PROTECTIVE SYSTEM, SEE SPECIAL PROVISIONS.


FOR FRP PROTECTIVE SYSTEM DETAILS AND UNDERWATER MORTAR REPAIRS, SEE ``PILE FRP PROTECTIVE SYSTEM DETAILS'' SHEET.

- ERI EPOXY RESIN INJECTION
- FRP PROTECTIVE SYSTEM
- SHOTCRETE REPAIRS
- PILE FOOTING RESTORATION  $\times \times$

▲ FRP PROTECTIVE SYSTEM BELOW WATERLINE MAY INCLUDE APPROVED UNDERWATER MORTAR REPAIRS



STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION







ACB8082119D74CD							
			SHEET NO.				
DOCUMENT NOT CONSIDERED FINAL UNLESS ALL	NO. 1	BY:	DATE:	NO.	BY:	DATE:	S-209 total sheets
SIGNATURES COMPLETED	2			4			355