

AS-BUILT REPAIR QUANTITY TABLE

BENT 143									
CAP REPAIRS	ESTIMATE		ACTUAL						
SHOTCRETE REPAIRS	- SF	- CF	SF	CF					
EPOXY RESIN INJECTION	4.0 LF			LF					
COLUMN REPAIRS	ESTIMATE		ACTUAL						
SHOTCRETE REPAIRS	8.9 SF	4.5 CF	SF	CF					
EPOXY RESIN INJECTION	- LF			LF					
PILE REPAIRS	ESTIMATE		ACTUAL						
FRP PROTECTIVE SYSTEM AWL	- SF		SF						
FRP PROTECTIVE SYSTEM BWL	363.0 SF			SF					

FOR CAP REPAIRS: VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS.

NOTES:

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

- FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.
- FOR CONCRETE REPAIR DETAILS, SEE "TYPICAL CAP, COLUMN & UNDERDECK REPAIR DETAILS" & "PILE CONCRETE RESTORATION DETAILS" SHEETS.
- FOR FOOTING, COLUMN, AND STRUT REPAIR DETAILS, SEE "PILE FOOTING RESTORATION" SHEET.
- FOR PILE CONCRETE RESTORATION, SEE SPECIAL PROVISIONS.
- FOR FRP PROTECTIVE SYSTEM, SEE SPECIAL PROVISIONS.
- FOR FRP PROTECTIVE SYSTEM DETAILS AND UNDERWATER MORTAR REPAIRS, SEE "PILE FRP PROTECTIVE SYSTEM DETAILS" SHEET.

ERI - EPOXY RESIN INJECTION

- FRP PROTECTIVE SYSTEM

- SHOTCRETE REPAIRS

- PILE FOOTING RESTORATION

♠ FRP PROTECTIVE SYSTEM BELOW WATERLINE MAY INCLUDE APPROVED UNDERWATER MORTAR REPAIRS

PROJECT NO. HB-001/
DARE COUNTY
BRIDGE NO. 270009



STATE OF NORTH CAROLINA

DEPARTMENT OF TRANSPORTATION

RALEIGH

BENT 143 WEST FACE

OCUMENT NOT CONSIDERED NO. BY:
FINAL UNLESS ALL
SIGNATURES COMPLETED 2

	REVISIONS						SHEET NO.
\Box	NO.	BY:	DATE:	NO.	BY:	DATE:	S-223
. []	1			3			TOTAL SHEETS
	2			4			355