

+

+

AS-BUILT REPAIR QUANTITY TABLE				
BENT 153				
CAP REPAIRS	ESTIMATE		ACTUAL	
SHOTCRETE REPAIRS	2.0 SF	1.0 CF	SF	CF
EPOXY RESIN INJECTION	- LF			LF
COLUMN REPAIRS	ESTIMATE		ACTUAL	
SHOTCRETE REPAIRS	46.2 SF	23.1 CF	SF	CF
EPOXY RESIN INJECTION	- LF		LF	
PILE REPAIRS	ESTIMATE		ACTUAL	
FRP PROTECTIVE SYSTEM AWL	- SF		SF	
FRP PROTECTIVE SYSTEM BWL	302.5 SF		SF	