

+

+

AS-BUILT REPA	AIR QUANTITY TABLE									
BENT 161										
CAP REPAIRS										
SHOTCRETE REPAIRS	9.8 SF	4.9 CF	SF	CF						
EPOXY RESIN INJECTION	_	LF		LF						
PILE REPAIRS										
PILE CONCRETE RESTORATION	70.0 SF	27.6 CF	SF	CF						
FRP PROTECTIVE SYSTEM AWL	201.	3 SF								
FRP PROTECTIVE SYSTEM BWL	73.2	2 SF								
BENT 162										
CAP REPAIRS										
SHOTCRETE REPAIRS	1.5 SF	0.8 CF	SF	CF						
EPOXY RESIN INJECTION	_	LF		LF						
PILE REPAIRS										
PILE CONCRETE RESTORATION	70.0 SF	27.5 CF	SF	CF						
FRP PROTECTIVE SYSTEM AWL	213.	5 SF								
FRP PROTECTIVE SYSTEM BWL	73.2	2 SF								
EAR CAR REPAIRS VALUES IN CHART REPRESENT ESTIMATER REPAIR TATALS										

FOR CAP REPAIRS: VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2" CL. TO SAWCUT. SEE REPAIR DETAILS. NOTES:

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIR DETAILS, SEE ``TYPICAL CAP, COLUMN & UNDERDECK REPAIR DETAILS'' & ``PILE CONCRETE RESTORATION DETAILS'' SHEETS. FOR PILE CONCRETE RESTORATION, SEE SPECIAL PROVISIONS.

FOR FRP PROTECTIVE SYSTEM, SEE SPECIAL PROVISIONS.

FOR FRP PROTECTIVE SYSTEM DETAILS AND UNDERWATER MORTAR REPAIRS, SEE ``PILE FRP PROTECTIVE SYSTEM DETAILS'' SHEET.

	ESTIMATED PILE CRACK QTY. TABLE								E	
E			NW	W	SW	S	SE	E	NE	N
NE SE BENT		PILE 1	3	1	_	3	_	7	7	5
	BENT	PILE 2	-	-	-	-	_	4	7	_
	161	PILE 3	6	1	3	3	12	4	7	7
NW SW		PILE 4	_	5	1	-	_	_	2	-
W		PILE 1	5	6	4	_	3	_	6	6
TEM BELOW UDE	BENT	PILE 2	7	-	4	_	3	2	7	3
R MORTAR	162	PILE 3	2	3	2	6	_	_	_	1
		PILE 4	1	-	3	3	2	_	1	2
NOTE: FOR INFORMATION ON PILE CONDITION ONLY.										
		PROJEC) T (NO.		- [3-(17	
N INJECTION	ľ		_					0		
rive system								ΛΤΥ		
ete restoration BRIDGE NO. 27					70($\bigcirc \bigcirc$	9			
REPAIRS]									
STATE OF NORTH CAROLINA							$\cap \mathbb{N}$			
	DEPARTMENT OF TRANSPORTATION Raleigh									
	FESS/ON THE									
	SEAL 20208									
	VGINEER &	REN	T	16	1 2	, F	RFN	NΤ	16	52
DEPARTMENT OF TRANSPORTATION RALEIGH BENT 161 & BENT 162 BENT 162										
DocuSigned by: F_{11} F_{12} $F_{14}/2022$										
ACB8082119D74CD										
le		NO, BY:		REVISIONS DATE: NO. BY: DAT				ATE:		EET NO. S-250
DOCUMENT NOT FINAL UNLE	CONSIDERED	цо. вт.	UAI	L.	NO.	BY:		AICI		TOTAL SHEETS
SIGNATURES C		2			<u></u>					355