

▲ FRP PROTECTIVE SYSTEM BELOW WATERLINE MAY INCLUDE APPROVED UNDERWATER MORTAR

ESTIMATED PILE CRACK QTY. TABLE										
		NW	W	SW	S	SE	E	NE	N	
BENT 247	PILE 1	9	_	_	_	_	_	8	8	
	PILE 2	6	8	_	4	4	5	_	3	
	PILE 3	_	_	6	4	3	_	_	4	
	PILE 4	-	-	-	7	-	13	-	_	
BENT 248	PILE 1	_	2	_	_	3	4	_	_	
	PILE 2	7	_	4	_	_	_	_	_	
	PILE 3	7	_	_	4	_	_	_	_	
	PILE 4	_	5	4	-	3	6	_	_	
NOTE: FOR INFORMATION ON PILE CONDITION ONLY.										

DARE

AS-BUILT REPAIR QUANTITY TABLE

BENT 247

- SF

BENT 248

- SF

FOR CAP REPAIRS: VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS

AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE

THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE

FOR CONCRETE REPAIR DETAILS, SEE "TYPICAL CAP, COLUMN & UNDERDECK

FOR FRP PROTECTIVE SYSTEM DETAILS AND UNDERWATER MORTAR REPAIRS,

REPAIR DETAILS" & "PILE CONCRETE RESTORATION DETAILS" SHEETS.

FOR PILE CONCRETE RESTORATION, SEE SPECIAL PROVISIONS.

FOR FRP PROTECTIVE SYSTEM, SEE SPECIAL PROVISIONS.

SEE "PILE FRP PROTECTIVE SYSTEM DETAILS" SHEET.

BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE

DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF

- LF

234.7 SF

66.0 SF

- LF

37.5 SF | 15.5 CF

165.0 SF

66.0 SF

- CF

- CF

SF

SF

SF

SF

CAP REPAIRS

PILE REPAIRS

FRP PROTECTIVE SYSTEM AWL

FRP PROTECTIVE SYSTEM BWL

CAP REPAIRS

PILE REPAIRS

FRP PROTECTIVE SYSTEM AWL

FRP PROTECTIVE SYSTEM BWL

REPAIR QUANTITY TABLE.

CL. TO SAWCUT. SEE REPAIR DETAILS.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

PILE CONCRETE RESTORATION

SHOTCRETE REPAIRS

NOTES:

EPOXY RESIN INJECTION

PILE CONCRETE RESTORATION | 112.5 SF | 42.4 CF

SHOTCRETE REPAIRS

EPOXY RESIN INJECTION

270009 BRIDGE NO._

PROJECT NO.

- SHOTCRETE REPAIRS



STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH

COUNTY

BENT 247 & BENT 248

OCUMENT NOT CON FINAL UNLESS SIGNATURES COM

		SHEET N					
ONSTDERED	NO.	BY:	DATE:	NO.	BY:	DATE:	S-293
S ALL	1			3			TOTAL SHEETS
MPLETED	2			4			355

ERI - EPOXY RESIN INJECTION

- FRP PROTECTIVE SYSTEM

- PILE CONCRETE RESTORATION

GANNETT One Glenwood Avenus Suite 900
Raleigh, NC 27603
FLEMING (919) 420-7660
NC Lic. No. F-0270

BENT 248

<u>~8.8 SF</u>

<u></u>7.5 SF

ELEVATION

EAST FACE

~7.5 SF

END VIEW

NORTH FACE

(AWL = ABOVE WATERLINE)
(BWL = BELOW WATERLINE)
(**QUANTITY INCLUDES ADJACENT REPAIRS)

END VIEW

SOUTH FACE

T. HARTLEY _ DATE : <u>2/2019</u> DATE : <u>4/2019</u> J. FARNHAM CHECKED BY : __

VIEW (TYP.) P2

ELEVATION

WEST FACE

APPROX.

NORMAL WATER SURFACE