





ESTIMATED PILE CRACK QTY. TABLE NW W SW S SE E NE N BENT 249 | 4 | - | 3 | 6 | 8 | 8 | 8 BENT 250

NOTE: FOR INFORMATION ON PILE CONDITION ONLY.

AS-BUILT REPAIR QUANTITY TABLE

BENT 249

BENT 250

FOR CAP REPAIRS: VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS

AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE

THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE

FOR CONCRETE REPAIR DETAILS, SEE "TYPICAL CAP, COLUMN & UNDERDECK REPAIR DETAILS" & "PILE CONCRETE RESTORATION DETAILS" SHEETS.

FOR FRP PROTECTIVE SYSTEM DETAILS AND UNDERWATER MORTAR REPAIRS,

BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF

28.4 SF | 14.2 CF

16.5 SF | 6.5 CF

181.5 SF

66.0 SF

38.5 SF | 19.3 CF

- LF

29.2 SF | 12.1 CF

213.6 SF

66.0 SF

- LF

SF

SF

SF

SF

CAP REPAIRS

PILE REPAIRS

FRP PROTECTIVE SYSTEM AWL

FRP PROTECTIVE SYSTEM BWL

CAP REPAIRS

PILE REPAIRS

FRP PROTECTIVE SYSTEM AWL

FRP PROTECTIVE SYSTEM BWL

REPAIR QUANTITY TABLE.

CL. TO SAWCUT. SEE REPAIR DETAILS.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR PILE CONCRETE RESTORATION, SEE SPECIAL PROVISIONS.

FOR FRP PROTECTIVE SYSTEM, SEE SPECIAL PROVISIONS.

SEE "PILE FRP PROTECTIVE SYSTEM DETAILS" SHEET.

PILE CONCRETE RESTORATION

SHOTCRETE REPAIRS

NOTES:

EPOXY RESIN INJECTION

PILE CONCRETE RESTORATION

SHOTCRETE REPAIRS

EPOXY RESIN INJECTION

HB-0017 PROJECT NO.___ DARE COUNTY

270009 BRIDGE NO. .

- SHOTCRETE REPAIRS

Ein Bhil Jr 7/14/2022

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH

BENT 249 & BENT 250

OCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

SHEET NO REVISIONS NO. BY: S-294 DATE: DATE: BY: TOTAL SHEETS 355

ERI - EPOXY RESIN INJECTION

- FRP PROTECTIVE SYSTEM - PILE CONCRETE RESTORATION

BENT 250

**17.3 SF —

UNWRAPPED— VIEW (TYP.)

ELEVATION

WEST FACE

(AWL = ABOVE WATERLINE) (BWL = BELOW WATERLINE) (**QUANTITY INCLUDES ADJACENT REPAIRS)

T. HARTLEY _ DATE : <u>2/2019</u> DATE : <u>4/2019</u> J. FARNHAM CHECKED BY : ___

11.9 SF —

APPROX.-

NORMAL WATER SURFACE

END VIEW ELEVATION SOUTH FACE

END VIEW EAST FACE NORTH FACE

GANNETT One Glenwood Avent Suite 900
Raleigh, NC 27603
(919) 420-7660
NC Lic. No. F-0270