

AS-BUILT REPAIR QUANTITY TABLE BENT 263

CAP REPAIRS	ESTIMATE			
SHOTCRETE REPAIRS	0.7 SF	0.4 CF	SF	CF
EPOXY RESIN INJECTION	- LF			LF
PILE REPAIRS	ESTIMATE			
PILE CONCRETE RESTORATION	8.8 SF	3.7 CF	SF	CF
FRP PROTECTIVE SYSTEM AWL	77.0 SF			
FRP PROTECTIVE SYSTEM BWL	33.0 SF			

CAP REPAIRS	ESTIMATE			
SHOTCRETE REPAIRS	- SF	- CF	SF	CF
EPOXY RESIN INJECTION	- LF			LF
PILE REPAIRS	ESTIMATE			
PILE CONCRETE RESTORATION	10.0 SF	4.2 CF	SF	CF
FRP PROTECTIVE SYSTEM AWL	137.5 SF			
FRP PROTECTIVE SYSTEM BWL	49.5 SF			

FOR CAP REPAIRS: VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIR DETAILS, SEE "TYPICAL CAP, COLUMN & UNDERDECK REPAIR DETAILS" & "PILE CONCRETE RESTORATION DETAILS" SHEETS.

FOR PILE CONCRETE RESTORATION, SEE SPECIAL PROVISIONS.

FOR FRP PROTECTIVE SYSTEM, SEE SPECIAL PROVISIONS.

FOR FRP PROTECTIVE SYSTEM DETAILS AND UNDERWATER MORTAR REPAIRS,

ESTIMATED PILE CRACK QTY. TABLE									
		NW	W	SW	S	SE	E	NE	Ν
BENT 263	PILE 1	_	_	_	_	_	_	_	_
	PILE 2	_	_	_	_	_	_	_	_
	PILE 3	_	=	3	_	3	=	5	5
	PILE 4	7	4	_	2	5	_	6	_
BENT 264	PILE 1	_	_	_	_	_	_	-	-
	PILE 2	8	_	_	6	4	4	8	-
	PILE 3	7	_	6	1	_	5	_	7
	PILE 4	7	-	2	-	3	-	-	-
OTE: FOR INFORMATION ON PILE CONDITION ONLY.									

DARE COUNTY

270009

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH

BENT 263 & BENT 264

355

SHEET NO REVISIONS NO. BY: DATE: OCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED TOTAL SHEETS