

Ρ4

ELEVATION

EAST FACE

END VIEW

SOUTH FACE

BENT 274

(AWL = ABOVE WATERLINE)
(BWL = BELOW WATERLINE)
(\*\*QUANTITY INCLUDES ADJACENT REPAIRS)

UNWRAPPED VIEW (TYP.)

\_ DATE : <u>2/2019</u> DATE : <u>4/2019</u>

T. HARTLEY

CHECKED BY : \_\_

J. FARNHAM

ELEVATION

WEST FACE

AS-BUILT REPAIR QUANTITY TABLE BENT 273 CAP REPAIRS SF SHOTCRETE REPAIRS 11.6 SF | 5.8 CF EPOXY RESIN INJECTION - LF PILE REPAIRS SF PILE CONCRETE RESTORATION | 25.3 SF | 10.3 CF FRP PROTECTIVE SYSTEM AWL 192.5 SF FRP PROTECTIVE SYSTEM BWL 66.0 SF BENT 274 CAP REPAIRS SF SHOTCRETE REPAIRS 1.4 SF | 0.7 CF - LF EPOXY RESIN INJECTION

FOR CAP REPAIRS: VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2 CL. TO SAWCUT. SEE REPAIR DETAILS.

36.4 SF | 14.6 CF

191.6 SF

66.0 SF

SF

## NOTES:

PILE REPAIRS

FRP PROTECTIVE SYSTEM AWL

FRP PROTECTIVE SYSTEM BWL

PILE CONCRETE RESTORATION

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.


FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIR DETAILS, SEE "TYPICAL CAP, COLUMN & UNDERDECK REPAIR DETAILS" & "PILE CONCRETE RESTORATION DETAILS" SHEETS.

FOR PILE CONCRETE RESTORATION, SEE SPECIAL PROVISIONS.

FOR FRP PROTECTIVE SYSTEM, SEE SPECIAL PROVISIONS.

FOR FRP PROTECTIVE SYSTEM DETAILS AND UNDERWATER MORTAR REPAIRS, SEE "PILE FRP PROTECTIVE SYSTEM DETAILS" SHEET.



▲ FRP PROTECTIVE SYSTEM BELOW WATERLINE MAY INCLUDE APPROVED UNDERWATER MORTAR

ESTIMATED PILE CRACK QTY. TABLE									
		NW	W	SW	S	SE	E	NE	Ν
BENT 273	PILE 1	_	_	_	8	_	_	_	4
	PILE 2	6	3	_	_	_	_	_	7
	PILE 3	5	6	7	=	_	_	_	8
	PILE 4	-	-	_	2	_	3	7	8
BENT 274	PILE 1	-	4	-	-	_	-	_	_
	PILE 2	_	-	_	-	_	4	_	6
	PILE 3	_	_	2	_	_	_	6	6
	PILE 4	_	_	_	_	3	7	5	6

NOTE: FOR INFORMATION ON PILE CONDITION ONLY.

ERI - EPOXY RESIN INJECTION

- FRP PROTECTIVE SYSTEM

- PILE CONCRETE RESTORATION

HB-0017 PROJECT NO. DARE COUNTY 270009 BRIDGE NO.

- SHOTCRETE REPAIRS



STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH

BENT 273 & BENT 274

SHEET NO

S-306

TOTAL SHEETS

355

REVISIONS NO. BY: DATE: DATE: OCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

Ein BML (h 7/14/2022 ACB8082119D74CD...

GANNETT One Glenwood Avenu Suite 900 Raleigh, NC 27603 (919) 420-7660 NC Lic. No. F-0270

END VIEW

NORTH FACE