

AS-BUILT REPAIR QUANTITY TABLE

BENT 275

| CAP REPAIRS | | | |
|---------------------------|----------|---------|-------|
| SHOTCRETE REPAIRS | 9.7 SF | 4.9 CF | SF CF |
| EPOXY RESIN INJECTION | - LF | | LF |
| PILE REPAIRS | | | |
| PILE CONCRETE RESTORATION | 33.9 SF | 13.6 CF | SF CF |
| FRP PROTECTIVE SYSTEM AWL | 186.1 SF | | |
| FRP PROTECTIVE SYSTEM BWL | 66.0 SF | | |

BENT 276

| CAP REPAIRS | | | |
|---------------------------|----------|--------|-------|
| SHOTCRETE REPAIRS | 5.5 SF | 2.8 CF | SF CF |
| EPOXY RESIN INJECTION | - LF | | LF |
| PILE REPAIRS | | | |
| PILE CONCRETE RESTORATION | 21.3 SF | 9.0 CF | SF CF |
| FRP PROTECTIVE SYSTEM AWL | 292.0 SF | | |
| FRP PROTECTIVE SYSTEM BWL | 99.0 SF | | |

FOR CAP REPAIRS: VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1" BEHIND REBAR AND MIN. 2" CL. TO SAWCUT. SEE REPAIR DETAILS.

NOTES:

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.


FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIR DETAILS, SEE "TYPICAL CAP, COLUMN & UNDERDECK REPAIR DETAILS" & "PILE CONCRETE RESTORATION DETAILS" SHEETS.

FOR PILE CONCRETE RESTORATION, SEE SPECIAL PROVISIONS.

FOR FRP PROTECTIVE SYSTEM, SEE SPECIAL PROVISIONS.


FOR FRP PROTECTIVE SYSTEM DETAILS AND UNDERWATER MORTAR REPAIRS, SEE "PILE FRP PROTECTIVE SYSTEM DETAILS" SHEET.



▲ FRP PROTECTIVE SYSTEM BELOW WATERLINE MAY INCLUDE APPROVED UNDERWATER MORTAR REPAIRS

(AWL = ABOVE WATERLINE) (BWL = BELOW WATERLINE)
(** QUANTITY INCLUDES ADJACENT REPAIRS)

BENT 275




ESTIMATED PILE CRACK QTY. TABLE

| BENT | PILE | DIRECTION | | | | | | | |
|------|--------|-----------|----|----|---|----|---|----|---|
| | | NW | W | SW | S | SE | E | NE | N |
| 275 | PILE 1 | 2 | 13 | - | - | - | - | - | 2 |
| | PILE 2 | - | - | - | - | - | - | - | 6 |
| | PILE 3 | 5 | 4 | - | - | 2 | - | 6 | - |
| | PILE 4 | - | 4 | - | 3 | 2 | 6 | 6 | 2 |
| 276 | PILE 1 | - | 3 | 3 | - | - | - | 4 | 2 |
| | PILE 2 | - | 5 | - | 2 | - | 3 | 4 | 9 |
| | PILE 3 | - | 4 | 6 | - | 7 | - | 9 | - |
| | PILE 4 | - | 12 | - | 2 | - | - | - | - |
| | PILE 5 | - | 7 | 4 | - | - | 4 | 4 | - |
| | PILE 6 | 6 | - | 3 | 3 | - | 5 | 7 | 5 |

NOTE: FOR INFORMATION ON PILE CONDITION ONLY.

PROJECT NO. HB-0017
DARE COUNTY
BRIDGE NO. 270009



STATE OF NORTH CAROLINA
DEPARTMENT OF TRANSPORTATION
RALEIGH

BENT 275 & BENT 276

ERI - EPOXY RESIN INJECTION PILE CONCRETE RESTORATION
FRP PROTECTIVE SYSTEM SHOTCRETE REPAIRS

BENT 276

(AWL = ABOVE WATERLINE)
(BWL = BELOW WATERLINE)
(** QUANTITY INCLUDES ADJACENT REPAIRS)

DRAWN BY: T. HARTLEY DATE: 2/2019
CHECKED BY: J. FARNHAM DATE: 4/2019



| REVISIONS | | | | | | SHEET NO. |
|-----------|-----|-------|-----|-----|-------|--------------|
| NO. | BY: | DATE: | NO. | BY: | DATE: | TOTAL SHEETS |
| 1 | | | 3 | | | 357 |
| 2 | | | 4 | | | 355 |

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED