



DRAWN BY :	T. HARTLEY	DATE : <u>2/2019</u>
CHECKED BY :	J. FARNHAM	DATE : <u>4/2019</u>

+

+



I						
AS-BUILT REPA	TY TA	BLE				
BENT 311						
CAP REPAIRS	ESTI	MATE				
SHOTCRETE REPAIRS	17.5 SF	8.8 CF	SF	CF		
EPOXY RESIN INJECTION	_	LF		LF		
PILE REPAIRS	ESTIMATE					
PILE CONCRETE RESTORATION	14.4 SF	6.1 CF	SF	CF		
FRP PROTECTIVE SYSTEM AWL	90.3 SF					
FRP PROTECTIVE SYSTEM BWL	66.0 SF					
B	ent 3	12				
CAP REPAIRS	ESTIMATE					
SHOTCRETE REPAIRS	74.6 SF	37.3 CF	SF	CF		
EPOXY RESIN INJECTION	- LF			LF		
PILE REPAIRS	ESTIMATE					
PILE CONCRETE RESTORATION	- SF	- CF	SF	CF		
FRP PROTECTIVE SYSTEM AWL	64.2 SF					
FRP PROTECTIVE SYSTEM BWL	49.5 SF					

FOR CAP REPAIRS: VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2 CL. TO SAWCUT. SEE REPAIR DETAILS. NOTES:

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIR DETAILS, SEE ``TYPICAL CAP, COLUMN & UNDERDECK REPAIR DETAILS" & "PILE CONCRETE RESTORATION DETAILS" SHEETS. FOR PILE CONCRETE RESTORATION, SEE SPECIAL PROVISIONS.

FOR FRP PROTECTIVE SYSTEM, SEE SPECIAL PROVISIONS.

FOR FRP PROTECTIVE SYSTEM DETAILS AND UNDERWATER MORTAR REPAIRS, SEE ``PILE FRP PROTECTIVE SYSTEM DETAILS' SHEET.

E	ESTIN	IATED P	ILE		RAC	KC	)ΤΥ	. TA	BL	_
NE			NW	W	SW	S	SE	E	NE	Ν
N S		PILE 1	_	-	_	2	_	2	-	_
	BENT	PILE 2	1	-	-	-	-	_	-	1
NW SW	311	PILE 3	_	1	-	-	2	_	-	1
W		PILE 4	_	-	-	_	-	_	-	-
		PILE 1	_	6	_	_	_	_	_	_
ROTECTIVE SYSTEM BELOW LINE MAY INCLUDE	BENT	PILE 2	_	1	1	_	_	-	-	_
VED UNDERWATER MORTAR RS	312	PILE 3	-	-	-	-	-	_	-	-
		PILE 4	-	1	-	_	-	-	-	3
	NOTE: FOR I	NFORMATIO	N ON	PIL	E CO	NDIT	ION	ONLY	°	
		PROJEC		NO.		$\left  - \right  \right $	∃ – (			
- EPOXY RESIN INJECTION			$\Box$	AR	F			$\cap$		ITV
- FRP PROTECTIVE SYSTEM										
- PILE CONCRETE RESTORATION BRIDGE NO. 270009										
- SHOTCRETE REPAIRS										
				STAT	E OF NO	RTH CAR	ROL TNA			
	DEPARTMENT OF TRANSPORTATION									
DEPARTMENT OF TRANSPORTATION RALEIGH DEVARTMENT OF TRANSPORTATION RALEIGH BENT 311 & BENT 312										
SEAL F										
	20208				1 0	F		. —		1
BENT 311 & BENT 312						12				
Ein Bhu ACB8082119D740	c 7/14/2022									
One Glenwood Avenue				REVIS	SIONS		1			EET NO.
Suite 900 Raleigh, NC 27603 (919) 420-7660		NO. BY:	DAT	E:	NO.	BY:	D	ATE:		5-325 Total
G (919) 420-7660 NC Lic. No. F-0270 SIGNATURES	LSS ALL Completed	1			<u>৩</u> 4				-   *	total sheets 355