
+

AS-BUILT REPAIR QUANTITY TABLE

	SUPE	RSTRUC	TURE F	REPAIRS	$\hat{\boldsymbol{\Sigma}}$							
		SPAN 1			SPAN 2				SPAN 3			
	ESTI	ESTIMATE		ACTUAL E		MATE	ACTUAL		ESTIMATE		ACTUAL	
	AREA	VOLUME	AREA	VOLUME	AREA	VOLUME	AREA	VOLUME	AREA	VOLUME	AREA	VOLUME
CONCRETE REPAIR AREA (CR)	SF	CF			SF	CF			2.0 SF	0.7 CF		
	AREA	VOLUME	AREA	VOLUME	AREA	VOLUME	AREA	VOLUME	AREA	VOLUME	AREA	VOLUME
SHOTCRETE REPAIR AREA (SCR)	SF	CF			2.4 SF	0.8 CF			2.0 SF	0.7 CF		
	ESTI	ESTIMATE ACTUAL		ESTIMATE		ACTUAL		ESTIMATE		ACTUAL		
CLEANING & PAINTING EXISTING BEARINGS WITH HRSCA	4	ЕА			8	ΕA			4	ΕA		



NOTES:

+

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE TABLE ABOVE. FOR CONCRETE AND SHOTCRETE REPAIRS, SEE "CONCRETE RESTORATION DETAILS" SHEETS.

SHOTCRETE REPAIRS MAY BE REPLACED WITH CONCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

FOR CLEANING & PAINTING EXISTING BEARINGS WITH HRSCA, SEE SPECIAL PROVISIONS.

FOR ZONE PAINTING OF EXISTING STRUCTURE, SEE SPECIAL PROVISIONS.

FOR DETAILS OF CLEANING AND PAINTING GIRDER ENDS (CPG), SEE "MISCELLANEOUS REPAIRS" SHEET.

DRAWN BY :	ALLEN J.MCSWAIN	DATE : <u>01/2022</u>
CHECKED BY :	JACOB H.DUKE	DATE : <u>01/2022</u>
DESIGN ENGINEER	OF RECORD: DIEGO A. AGUIRE	<u>RE</u> date : <u>01/2022</u>

4/21/2022 I5915B_SMU_SSR01_480096.dgn daguirre

LEGEND:



CLEAN AND PAINT GIRDER ENDS (5 LF)

- CLEAN AND PAINT BEARING