DECK UNDERSIDE REPAIR QUANTITY TABLE **NOTES** REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN BASED ON THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE SPAN B **ESTIMATE** DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE AREA VOLUME SHOTCRETE REPAIRS REPAIRS AND ENTER THE ACTUAL QUANTITIES INTO THE REPAIR QUANTITY TABLE. CONCRETE REPAIRS MAYBE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH UNDERSIDE OF DECK 0 THE APPROVAL OF THE ENGINEER. CONCRETE DIAPHRAGM ALL GIRDERS SHALL BE PAINTED IN ACCORDANCE WITH THE LIMITS OF ZONE PAINTING **OVERHANG** 0 DETAIL. VOLUME AREA CONCRETE REPAIRS SHOTCRETE REPAIR AREA UNDERSIDE OF DECK 0 CONCRETE DIAPHRAGM 0 CONCRETE REPAIR AREA OVERHANG VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER MIN. 2" CLEAR TO SAWCUT. SEE REPAIR DETAILS. (G1) ← INTERMEDIATE DIAPHRAGM (G4) ← **Q** BENT 2 \_ Q GIRDER (TYP.) © BENT 1 —∕ (G6) SPAN B WAKE BRIDGE NO. \_\_\_ SHEET 2 OF 3 ZONE PAINTING ZONE PAINTING PAINTING

LIMITS OF ZONE PAINTING

QUANTITIES ACTUAL AREA VOLUME SF AREA VOLUME

REMOVAL OF UNSOUND CONCRETE, MIN. OF 1" BEHIND REBAR AND

PROJECT NO. 15BPR.59 COUNTY

911039

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION DECK UNDERSIDE REPAIR

SPAN B

REVISIONS DATE:

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

12/08/2022

SHEET NO. S2-13

D.A. CANTRELL/A.Y. GODFREY

. N.A. PIERCE

DATE: 09/2022

10/2022

DATE: 12/2022