

-588 + ++ $\Box$ 01/ + ) | ( Σ Σ  $\square$ 

| UNDERSIDE OF DECK REPAIR   |            |              |            |              |  |
|----------------------------|------------|--------------|------------|--------------|--|
|                            | ESTIMATE   |              | ACTUAL     |              |  |
| HOTCRETE REPAIR            | AREA<br>SF | VOLUMN<br>CF | AREA<br>SF | VOLUMN<br>CF |  |
| RSIDE OF DECK              | 0.0        | 0.0          |            |              |  |
| HANG DIAPHRAGMS            | 0.0        | 0.0          |            |              |  |
| RSIDE OF OVERHANG          | 0.0        | 0.0          |            |              |  |
| RIOR DIAPHRAGMS            | 0.0        | 0.0          |            |              |  |
|                            |            |              |            |              |  |
|                            | ESTIMATE   |              | ACTUAL     |              |  |
| RSIDE EPOXY RESIN<br>CTION | 0.0 LF     |              |            |              |  |
|                            | -          |              |            |              |  |



| BRIDGE RAIL QUANTITIES                           |        |  |  |  |
|--|--------|--|--|--|
| REMOVE 20"TUBULAR STEEL<br>BEAM GUARDRAIL        | 485 LF |  |  |  |
| 20" TUBULAR STEEL BEAM GUARDRAIL                 | 465 LF |  |  |  |
| REMOVE AND REPLACE W 6X9 POSTS                   | 6 EA   |  |  |  |
| W-TR STEEL BEAM GUARDRAIL<br>TRANSITION SECTIONS | 3 EA   |  |  |  |

