

REMOVE SURFACE CONCRETE TO VERIFY THAT SAW CUT DEPTH WILL

NOT DAMAGE EXISTING REINFORCING STEEL.

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL

OF UNSOUND CONCRETE, MINIMUM OF 1" BEHIND REBAR AND MINIMUM OF 2" CLEARANCE TO SAWCUT. FOR REPAIR DETAILS, SEE "TYPICAL CAP AND

COLUMN REPAIR DETAILS" SHEET.

MATCH LINE

END VIEW

(SHOWING LOWER PORTION)

BUNCOMBE

Ein BML On 7/25/2022

DOCUMENT NOT CONSIDERED

FINAL UNLESS ALL

SIGNATURES COMPLETED

One Glenwood Avenue

Raleigh, NC 27603

NC L1c.No. F-0270

919-420-7660

Suite 900

(COLUMN 3)

100344

DATE:

STATE OF NORTH CAROLINA

DEPARTMENT OF TRANSPORTATION

RALEIGH

BENT 3

SPAN C SIDE

NO. BY:

REVISIONS

DATE:

BY:

COUNTY

SHEET NO.

S3-15

TOTAL SHEETS

CONST. JOINT

TOP OF BENT CAP

DRAWN BY :

CHECKED BY : ___

J. MYA

J. YANNACCONE

91

_ DATE : <u>6/2022</u>

_ DATE : <u>6/2022</u>