


	DECK UNDERSIDE	REPAIR	QUANT	ITY TAI	BLE	
DEC	DECK UNDERSIDE REPAIRS	QUANTITIES				
	SPAN A	ESTIN	ESTIMATE		UAL	
SHO	OTCRETE REPAIRS	AREA SF	VOLUME CF	AREA SF	VOLUME CF	
UNE	DERSIDE OF DECK	0	0			
CON	ICRETE DIAPHRAGM	0.5	0.4			
OVE	RHANG	0	0			
1						
	NCRETE REPAIRS	AREA SF	VOLUME CF	AREA SF	VOLUME CF	
UNE	DERSIDE OF DECK	0	0			
CON	ICRETE DIAPHRAGM	0	0			
OVE	RHANG	0	0			
EPO	OXY RESIN INJECTION	LINEAR FT		LINEAR FT		
CON	ICRETE DIAPHRAGM	0				
COI	NCRETE OVERHANG	0				
ZOI	NE PAINTING		AREA SF		AREA SF	
BEA	M ENDS		225.4			


VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1" BEHIND REBAR AND MIN. 2" CLEAR TO SAWCUT. SEE REPAIR DETAILS.



SHOTCRETE REPAIR AREA



CONCRETE REPAIR AREA



ZONE PAINTING



EPOXY RESIN INJECTION



BEAM NUMBER

WEB PLATING REPAIR

BOTTOM FLANGE PLATING REPAIR

BOLTED WEB PLATE REPAIR


BOLTED FLANGE PLATE REPAIR

BEAM REPAIR QUANTITIY TABLE							
BOLTED STEE	L PLATES	STEEL PI	_ATES	STEEL DIAF	PHRAGM	BEAM REPA	IR CUT-OUT
LBS.	1	LBS.		LBS.		LBS.	
ESTIMATE	ACTUAL	ESTIMATE	ACTUAL	ESTIMATE	ACTUAL	ESTIMATE	ACTUAL
0.0		0.0		0.0		0.0	

ANTICIPATED STEEL REPAIR LOCATIONS								
REPAIR TYPE	BEAM	LOCATION	DIM. "A"	DIM. "B''	DIM. "C''	DIM. "D''		
W								
ВС								
F								
BW								
BF								

(SEE SHEETS S2-26, S2-27 AND S2-28 FOR BEAM REPAIR DETAILS AND DIMENSIONS.)

__ DATE : <u>1/31/23</u> __ DATE : <u>5/31/23</u> S. T. SANDOR DRAWN BY : . W. C. SMITH CHECKED BY :



LIMITS OF ZONE PAINTING

B-5981 PROJECT NO.____ **DUPLIN** __ COUNTY

BRIDGE NO. 300017

SHEET 1 OF 5

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION

DECK UNDERSIDE REPAIR SPAN A

William C. Smith 10/24/2023

SEAL 054816

SHEET NO. REVISIONS S2-10 NO. BY: DATE: DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

10/17/2023 R:\Structures\Plans\300017\402_019_B5981_SMU_DUR_A_S2-10_300017.dgn