
Masonry Plan
Abbotts Creek
M.T. 316.3
Dec. 26.1902
J. Lee
Alignment
Tangent
Base of Rail
Level
High Water
Bed of Stream
Note
Coping on both abutments should be renewed.
Too thin and has been damaged by fire.