

SPAN 16

REPAIR TYPES

- (1) - CROSSFRAME / CONNECTION PLATE REPAIR
- (2*) - NUT AND BOLT REPAIR AT ANCHOR BOLT
- (2**) - NUT AND BOLT REPAIR AT PARKING BRACKET CONNECTION PLATE
- (2***) - NUT AND BOLT REPAIR AT CROSSFRAME CONNECTION PLATE
- (3) - PARKING AREA BRACKET CONNECTION PLATE REPAIR
- (4) - CROSSFRAME / FILL PLATE REPAIR
- (5) - PARKING AREA BRACKET DRIP BEAD ADDITION

PROJECT NO. 15BPR.15

NEW HANOVER COUNTY

STATION:

SHEET 2 OF 4

STATE OF NORTH CAROLINA
DEPARTMENT OF TRANSPORTATION
RALEIGH

APPROACH SPANS

STRUCTURAL STEEL REPAIR LOCATIONS

MODJESKI and MASTERS
Experience great bridges.

333 FAYETTEVILLE STREET, SUITE 505
RALEIGH, NC 27601
NC LICENSE NO. C-2979

NORTH CAROLINA PROFESSIONAL SEAL 032967 ENGINEER JASON R. DOUGHTY
12/20/17
DocuSigned by: Jason R Doughty
5F73FA2DEA974E8...

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

DESIGNED BY:	J. BORUTA	DATE :	NOV 2017
DRAWN BY:	K. WHITE	DATE :	NOV 2017
CHECKED BY:	B. LOFLIN	DATE :	DEC 2017
DESIGN ENGINEER OF RECORD:	J. DOUGHTY	DATE :	DEC 2017

REVISIONS

NO.	BY:	DATE:	NO.	BY:	DATE:
1			3		
2			4		

SHEET NO. S-34

TOTAL SHEETS 66

12/21/2017
400.067.368202.SMU_RA6.640013.dgn