DocuSign Envelope ID: 067AF060-EE70-4284-8B37-687A9E72BE3D

PROJECT REFERENCE NO.	SHEET NO.
C-5558	SIG. 2.15

SUMMARY OF WORK BY INTERSECTION

Reference Information						Controller,Cabinet & Foundation Work																										
						2070 Controller		Type 170 Cabinet		Install New Controller & Cabinet																						
													Install New Foundation																			
	NCDOT / City Signal Inv. No.	Intersection Name	Cable Routing Sheet Number	Signal Design Sheet Number	In / near historically significant area (see box note at bottom of page)	New	Existing	New	Existing	New Aux File for Cabinet	No. of New Detector Cards	**Base 332**	Adjacent to Existing	In Same Place as Existing	Relocated to (quadrant)	Comment	Terminal Splice Box	Modify Foundation	Remove Existing Foundation	Rotate Front of Cabinet clockwise (degrees)	Base Extender	Base Adapter	Integrated Base Adapter - Type 1 *	Integrated Base Adapter - Type 2 *	Integrated Base Adapter - Type 3 *	Integrated Base Adapter - Type 4 *	**Pole (336S)**	Ex. Height - Ground to Bottom (inches)	Replace concrete (SF)	Replace Asphalt **	Replace Brick (SF)
121	07-1483	SR 1300 (E. Green Drive) at Brentwood Street	CRP-6.140	Sig. 121.0		1		1		1	9	1						1		0	1											
122	07-1524	NC 62 (Liberty Road) at SR 4012 (Aldridge Rd) / NC 610 (E. Fairfield Rd)	CRP-6.079	Sig. 122.0		1		1			5	1								0												
123	07-1525	NC 68 (Eastchester Drive) at SR 1837 (Clinard Farms Road) / SR 4229 (Piedmont Parkway)	CRP-6.306	Sig. 123.0		1		1			9	1						1		90	1											
124	07-1527	NC 68 (Eastchester Drive) at SR 1536 (Penny Road)	CRP-6.301	Sig. 124.0		1		1		1	10	1						1		0	1											
125	07-1528	SR 4241 (Guilford Road) at SR 1545 (East Fork Road)	CRP-6.263	Sig. 125.0		1		1		1	5	1						1		0												
126	07-1578	SR 1113 (E. Kivett Drive) at I-85 Bus. / US 29 SB - US 70 WB Ramps	CRP-6.130	Sig. 126.0		1		1		1	4	1								0	1											
127	07-1579	SR 1113 (E. Kivett Drive) at I-85 Bus. / US 29 NB - US 70 EB Ramps	CRP-6.130	Sig. 127.0		1		1			4	1								0	1											
128	07-1592	I-74 WB / US 311 NB Ramps at SR 1486 (Greensboro Road)	CRP-6.249	Sig. 128.0		1		1		1	5	1								0	1											
129	07-1593	I-74 EB / US 311 SB Ramps at SR 1486 (Greensboro Road)	CRP-6.248	Sig. 129.0		1		1			5	1								0	1											
130	07-1603	NC 68 (Eastchester Drive) at Regency Drive	CRP-6.308	Sig. 130.0		1		1			8	1						1		90	1											
131	07-1623	I-74 WB /US 311 NB Ramps at NC 68 (Eastchester Drive)	CRP-6.290	Sig. 131.0		1		1		1	6	1						1		0	1											
132	07-1624	I-74 EB / US 311 SB Ramps at NC 68 (Eastchester Drive)	CRP-6.290	Sig. 132.0		1		1			7	1		1					1	0	1											
133	07-1735	I-74 WB / US 311 NB Ramps at Johnson Street	CRP-6.207	Sig. 133.0		1		1		1	5	1						1		0	1											
134	07-1736	SR 1003 (N. Main Street) at SR 1980 (Old Plank Road)	CRP-6.187	Sig. 134.0		1		1		1	5	1						1		0	1											
135	07-1737	SR 1541 (W. Wendover Avenue) at SR 4229 (Piedmont Parkway)	CRP-6.320	Sig. 135.0		1		1			15	1						1		0	1											
136	07-1744	SR 1896 (E. Hartley Drive) at Johnson Street	CRP-6.201	Sig. 136.0		1		1			14	1						1		0	1											
137	07-1745	SR 1896 (E. Hartley Drive) at W. Mall Lane / HPB Insurance Group	CRP-6.283	Sig. 137.0		1		1		1	7	1		1		adjust location so foundation does not impact sidewalk			1	0		1										
138	07-1746	SR 1896 (E. Hartley Drive) at E. Mall Lane / Lakewood Drive	CRP-6.284	Sig. 138.0		1		1		1	8	1		1					1	0		1										
139	07-1747	NC 68 (Eastchester Drive) at SR 1896 (E. Hartley Drive) / SR 1278 (N. College Drive)	CRP-6.285	Sig. 139.0		1		1			12	1						1		0	1											
140	07-1748	NC 68 (Eastchester Drive) at North Mall Lane	CRP-6.286	Sig. 140.0		1		1		1	8	1		1					1	0		1										
141	07-1834	SR 1541 (W. Wendover Avenue) at Morris Farm Drive	CRP-6.317	Sig. 141.0		1		1		1	7	1						1		0	1											
142	07-1853	SR 1545 (East Fork Road) at SR 1536 (Penny Road)	CRP-6.324	Sig. 142.0		1		1		1	4	1																				
143	07-1856	NC 68 (Eastchester Drive) at Premier Drive	CRP-6.302	Sig. 143.0		1		1			9	1						1		0	1											
144	07-1857	SR 1541 (W. Wendover Avenue) at Premier Drive / Windstream Way	CRP-6.314	Sig. 144.0		1		1			7	1						1		0		1										

* Includes new electrical service, special base adapter, intercepting and rerouting conduit for electrical service and all work associated with electrical service and grounding as described in the special provisions section for "Special Cabinet Base Adapter". See Special Provisions for explanation of Types.

** Replace Asphalt will be paid for under the same pay item as concrete sidewalk. See Project Special Provisions.

- Work shown on this sheet is for the upgrade of the traffic signals, including installation of new controllers and cabinets, new or modified foundations, electrical service and miscellaneous signal related items. Additional information can be found in the signal plans in this Volume. Work to be done for fiber-optic cable routing and interconnection is shown on the cable layout plans and on the sheets entitled "Summary of Work by Cable Layout Plans" in Volume I of III.
- The items listed above are for informational purposes only and represent work that is necessary to complete the contract and are not necessarily pay items. See Summary of Quantites and the Project Special Provisions for defined Pay Items for this contract.

This area has been determined to contain properties with documented historic significance. If it is necessary to deviate from these plans in this area, alert the Engineer to contact Project Development and Environmental Analysis Branch – Historic Architecture Group of the North Carolina Department of Transportation for an effects determination before proceeding.

ATKINS 1616 EAST MILLBROOK ROAD, SUITE 310
RALEIGH, NORTH CAROLINA 27609
(919) 876-6888 NCBEES #F-0326

Prepared for the Offices of: Transportation Mobility and Safety Division, State of North Carolina Department of Transportation, Intelligent Transportation Systems Section
750 Greenfield Parkway, Garner, NC 27529

NA

High Point Signal System
Summary of Work by
Intersection (sheet 1 of 3)

Division 7 Guilford County High Point

PLAN DATE:	June 2015	REVIEWED BY:	MB Toth
PREPARED BY:		REVIEWED BY:	LM Moon

REVISIONS	INIT.	DATE

SEAL
NORTH CAROLINA PROFESSIONAL SEAL 025892 ENGINEER MELISSA B. TOTH

DocuSigned by: Melissa B. Toth 6/5/2015
DATE

CADD Filename: SIG 2.15.dgn

08-JUN-2015 10:09
R:\Transportation\Traffic\Curr\R100037777 - High Point Sig Sys\Special Details\Volume III\SIG 2.15.dgn
WILLE2294 A: 0D8290140