



**TOTAL BILL OF MATERIAL**

BRIDGE	CONCRETE REPAIRS	SHOTCRETE REPAIRS	EPOXY RESIN INJECTION	CLEANING AND PAINTING OF EXISTING WEATHERING STEEL BRIDGE NO....	PAINTING CONTAINMENT FOR BRIDGE NO....	POLLUTION CONTROL	EPOXY OVERLAY SYSTEM MECHANICALLY DISTRIBUTED	BRIDGE JOINT DEMOLITION	* CONCRETE DECK REPAIR FOR EPOXY OVERLAY	ELASTOMERIC CONCRETE	EPOXY COATING	FOAM JOINT SEALS
	CU. FT.	CU. FT.	LIN. FT.	LUMP SUM	LUMP SUM	LUMP SUM	SQ. FT.	SQ. FT.	SQ. FT.	CU. FT.	SQ. FT.	LUMP SUM
GUILFORD #110	—	—	—	LUMP SUM	LUMP SUM	LUMP SUM	12188	115	10	31	—	LUMP SUM
GUILFORD #111	—	—	—	LUMP SUM	LUMP SUM	LUMP SUM	12103	115	10	31	—	LUMP SUM
GUILFORD #142	3	3	7	LUMP SUM	LUMP SUM	LUMP SUM	16176	216	10	54	1084	LUMP SUM
GUILFORD #144	6	1	52	LUMP SUM	LUMP SUM	LUMP SUM	16711	226	10	57	1153	LUMP SUM
<b>TOTAL</b>	<b>9</b>	<b>4</b>	<b>59</b>	<b>LUMP SUM</b>	<b>LUMP SUM</b>	<b>LUMP SUM</b>	<b>57178</b>	<b>672</b>	<b>40</b>	<b>173</b>	<b>2237</b>	<b>LUMP SUM</b>

\* CONCRETE DECK REPAIR FOR EPOXY OVERLAY IS NOT ANTICIPATED.  
 TOKEN PAY ITEM IS INDICATED FOR PRICING PURPOSES, IN CASE  
 UNANTICIPATED SURFACE PREPARATION AREAS ARE ENCOUNTERED.

**PROJECT NO. I-5789**  
**GUILFORD COUNTY**  
**BRIDGE NO. 110, 111, 142 & 144**

DocuSigned by:  
  
 E06BC490C...  


5/4/2016

STATE OF NORTH CAROLINA  
 DEPARTMENT OF TRANSPORTATION  
 RALEIGH

**TOTAL BILL OF MATERIAL**

DRAWN BY : S. T. SANDOR DATE : 02/2018  
 CHECKED BY : W. M. CLARKE DATE : 02/2018

REVISIONS						SHEET NO.
NO.	BY:	DATE:	NO.	BY:	DATE:	S-1
1			3			TOTAL SHEETS 37
2			4			

DOCUMENT NOT CONSIDERED  
 FINAL UNLESS ALL  
 SIGNATURES COMPLETED