## NOTE

CONTRACTOR SHALL SAW CUT TO A NOMINAL DEPTH OF  $1\!\!/_2$  BUT REINFORCING STEEL SHALL NOT BE DAMAGED.

CONTRACTOR SHALL REMOVE SURFACE CONCRETE TO VERIFY THAT SAWCUT DEPTH WILL NOT DAMAGE EXISTING REINFORCING STEEL.


CONTRACTOR SHALL SAW CUT THE REPAIR AREAS SO THAT THE CORNERS ARE SQUARE AS INDICATED ON THE DETAILS.

CONCRETE REPAIRS MAY BE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.


FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.





2" (MIN.)



- SPALLED, DELAMINATED OR CRACKED CONCRETE (REMOVE UNTIL SOUND CONC. IS FOUND AND A MIN. 1"BEHIND ANY EXPOSED REBAR)

<u>ELEVATION OF CAP</u>

PROJECT NO. I-5789

GUILFORD COUNTY

BRIDGE NO. 142 & 144

## COLUMN REPAIR



3/31/2016


SUBSTRUCTURE


STATE OF NORTH CAROLINA

DEPARTMENT OF TRANSPORTATION

TYPICAL CAP AND COLUMN REPAIR DETAILS

			_						
			REVISIONS					SHEET N	
DOCUMEN	IT NOT	CONSIDERED	NO.	BY:	DATE:	NO.	BY:	DATE:	S-34
FINA		ESS ALL	1			3			TOTAL SHEETS
SIGNATURES COMPLETED			2			4			37





SECTION THRU CAP

(EXAMPLE ONLY, ACTUAL REBAR
SIZES & LOCATIONS MAY VARY)

CAP REPAIR

 DRAWN BY :
 S. T. SANDOR
 DATE : 02/2016

 CHECKED BY :
 W.M. CLARKE
 DATE : 02/2016

31-MAR-2016 06:46 R:\Structures\DGN\404\_071\_I589\_SMU\_S34\_BR.dgn ssandor