




PLAN



ELEVATION (EAST FACE)

END BENT 1





ELEVATION (WEST FACE)

END BENT 2

PLANS PREPARED BY:

2610 Wycliff Road
Suite 102
Raleigh NC 27607-3073
(919) 420-7660

	AS-BUILT REPAIR QUANTITY TABLE					
	END BENT 1	QUANTITIES				
		ESTIMATE		ACTUAL		
	SHOTCRETE REPAIRS	AREA SF	VOLUME CF	AREA SF	DEPTH FT	VOLUME CF
	CAP (VERTICAL FACE)	8.5	4.2			
	CAP (HORIZONTAL, CORNER)	0	0			
	END BENT 2	QUANTITIES				
		ESTIMATE		ACTUAL		
	SHOTCRETE REPAIRS	AREA SF	VOLUME CF	AREA SF	DEPTH FT	VOLUME CF
	CAP (VERTICAL FACE)	45.6	22.8			
	CAP (HORIZONTAL, CORNER)	37.8	18.9			
VALUES IN CHART DEPOSEDIT ESTIMATED DEPATR TOTALS AFTER						

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS.

NOTES:

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.


SHOTCRETE REPAIRS MAY BE REPLACED WITH CONCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN REPAIR DETAILS"SHEET.

- SHOTCRETE REPAIR - CONCRETE REPAIR

> PROJECT NO. I-5889A BUNCOMBE _ COUNTY 344 BRIDGE NO. -



END BENT 1 & 2

DocuSigned by:

Eir BML 9

11/16/2017

BA9F91762D7044A... REVISIONS SHEET NO. NO. BY: S-27 DATE: OCUMENT NOT CONSIDEREI FINAL UNLESS ALL SIGNATURES COMPLETED TOTAL SHEETS

__ DATE : <u>9/2017</u> __ DATE : <u>10/2017</u> D.PETRY DRAWN BY : ___ R.F. WERTMAN

Excellence Delivered As Promised NC Lic. No. F-0270