

+

+

## AS-BUILT REPAIR QUANTITY TABLE


TOP OF DECK REPAIRS						
	ESTIMATE	ACTUAL				
SCARIFYING BRIDGE DECK	475 SQ.YDS.					
CLASS II SURFACE PREPARATION	11.3 SQ. YDS.					
CONCRETE DECK REPAIR FOR PPC OVERLAY	11.3 SQ. YDS.					
SHOTBLASTING BRIDGE DECK	475 SQ.YDS.					
PPC MATERIALS	16.5 CU. YDS.					
PLACING AND FINISHING PPC OVERLAY	475 SQ.YDS.					
GROOVING BRIDGE FLOORS	3999 SQ.FT.					

TOP OF DECK REPAIR QUANTITIES REPRESENT ESTIMATED VALUES OF CLASS II SURFACE PREPARATION AND CONCRETE DECK REPAIR FOR PPC OVERLAY AFTER REMOVAL OF UNSOUND CONCRETE (MIN. 2"CLEAR TO SAWCUT). SEE OVERLAY SURFACE PREPARATION FOR POLYESTER POLYMER CONCRETE SPECIAL PROVISION.

## NOTES:

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE BASED ON THE BEST INFORMATION AVAILABLE.IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER,THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ENTER THE ACTUAL QUANTITIES INTO THE AS-BUILT REPAIR QUANTITY TABLE.

FOR SECTION A-A, SEE "JOINT DETAILS" SHEET.



		CKLEN	<u>IBUR</u>	<u>C-5825</u> <u>G</u> co 207	5 UNTY		
SHEET 2 OF 3							
DocuSigned by: Micholas Pierce 3/2/2018 15110B434D0B485	STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH PLAN OF SPAN SPAN B						
DOCUMENT NOT CONSIDERED FINAL UNLESS ALL	NO. ВҮ: 1	DATE:	NO. BY:	DATE:	S-8 TOTAL SHEETS		
SIGNATURES COMPLETED	2		a.		31		