

AS-BUILT REPAIR QU	JANTITY	TABLE				
TOP OF DECK REPAIRS						
	ESTIMATE	ACTUAL				
SCARIFYING BRIDGE DECK	219 SQ.YDS.					
CLASS II SURFACE PREPARATION	*0.5 SQ.YDS.					
CONCRETE DECK REPAIR FOR PPC OVERLAY	*0.5 SQ.YDS.					
SHOTBLASTING BRIDGE DECK	219 SQ. YDS.					
PPC MATERIALS	7.6 CU.YDS.					
PLACING AND FINISHING PPC OVERLAY	219 SQ. YDS.					
GROOVING BRIDGE FLOORS	1699 SO.FT.					

TOP OF DECK REPAIR QUANTITIES REPRESENT ESTIMATED VALUES OF CLASS II SURFACE PREPARATION AND CONCRETE DECK REPAIR FOR PPC OVERLAY AFTER REMOVAL OF UNSOUND CONCRETE (MIN. 2"CLEAR TO SAWCUT). SEE OVERLAY SURFACE PREPARATION FOR POLYESTER POLYMER CONCRETE SPECIAL PROVISION.

DRAWN BY : _	E.K.POPE DA	TE : 1/18
CHECKED BY :		TE : 1/18

+

PLAN

NOTES:

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE BASED ON THE BEST INFORMATION AVAILABLE.IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER,THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ENTER THE ACTUAL QUANTITIES INTO THE AS-BUILT REPAIR QUANTITY TABLE.

FOR SECTION A-A, SEE "JOINT DETAILS" SHEET.

*CLASS II SURFACE PREPARATION AND CONCRETE REPAIR FOR PPC OVERLAY ARE NOT ANTICIPATED.A TOKEN PAY ITEM IS INDICATED FOR PRICING PURPOSES IN THE EVENT UNANTICIPATED CLASS II AREAS ARE ENCOUNTERED.

	PROJECT NO. <u>I-5825</u> <u>MECKLENBURG</u> COUNTY BRIDGE NO. <u>215</u> SHEET 3 OF 4					
NITHORTH CAROLINA	STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH					
Z O37479	PLAN OF SPAN					
DocuSigned by:	SPAN C					
DocuSigned by: Nicholas Pierce 3/2/2018 15110B434D0B485						
	REVISIONS SHEET NO.				SHEET NO.	
DOCUMENT NOT CONSIDERED	NO. BY:	DATE:	NO. BY:	DATE:	S-21	
FINAL UNLESS ALL	1		3		TOTAL SHEETS	
SIGNATURES COMPLETED	2		4		31	