This electronic collection of documents is provided for the convenience of the user and is Not a Certified Document –

The documents contained herein were originally issued and sealed by the individuals whose names and license numbers appear on each page, on the dates appearing with their signature on that page.

This file or an individual page shall not be considered a certified document.

STATE	OF	NORT	Ή	CAROLINA
DIVI	SION	N OF	HIC	GHWAYS

FORSYTH COUNTY

STATE	8	SHEET NO.	TOTAL SHEETS		
N.C.		I-5795	3A		
STATI	PROJ. NO.	F. A. PROJ. NO.	DESCRIPTION		
530	34.1.2	_	P.E.		
530	34.3.1	NHPP-0040(032)	CONST.		

LOCATION: FORSYTH COUNTY:

BRIDGE No. 330161 ON I-40 EBL OVER MUDDY CREEK

BRIDGE No. 330162 ON I-40 WBL OVER MUDDY CREEK BRIDGE No. 330444 ON US 421 SBL RAMP OVER I-40 & I-40 BUS

BRIDGE No. 330448 ON I-40 EBL OVER WESTGATE DRIVE

BRIDGE No. 330449 ON I-40 WBL OVER WESTGATE DRIVE BRIDGE No. 330508 ON I-40 WBL OVER I-40 BUS EBL


BRIDGE No. 330509 ON I-40 WBL RAMP OVER I-40 BUS AND US 421 EBL


INDEX OF STRUCTURES SHEETS

SHEET No.	DESCRIPTION	SHEET No.	DESCRIPTION	SHEET No.	DESCRIPTION	SHEET No.	DESCRIPTION
STRUCTURI	E No. 330161	STRUCTUR	No. 330444	STRUCTURE	No. 330449	STRUCTURE	No. 330509
<i>S15–01</i>	GENERAL DRAWING	<i>S17–01</i>	GENERAL DRAWING	S19-01	GENERAL DRAWING	S21-01	GENERAL DRAWING
<i>S15–02</i>	TYPICAL SECTION	<i>S17–02</i>	GENERAL DRAWING	<i>S19–02</i>	TYPICAL SECTION	<i>S21–02</i>	GENERAL DRAWING
<i>S15–03</i>	DECK SURFACE REPAIR	<i>\$17–03</i>	TYPICAL SECTION	<i>S19–03</i>	DECK SURFACE REPAIR	<i>S21–03</i>	TYPICAL SECTION
<i>\$15–04</i>	DECK UNDERSIDE REPAIR	<i>S17–04</i>	DECK SURFACE REPAIR	<i>S19–04</i>	JOINT DETAILS	<i>S21–04</i>	DECK SURFACE REPAIR SPANS A &
<i>S15–05</i>	JOINT DETAILS	<i>\$17–05</i>	DECK SURFACE REPAIR	<i>S19–05</i>	END BENTS	<i>S21–05</i>	DECK SURFACE REPAIR SPAN C
<i>S15–06</i>	END BENTS	<i>S17–06</i>	JOINT DETAILS	<i>S19–06</i>	BENT	<i>S21–06</i>	DECK SURFACE REPAIR SPAN D
<i>\$15–07</i>	BENT	<i>S17–07</i>	JOINT DETAILS	STRUCTURE	No. 330508	<i>S21–07</i>	DECK SURFACE REPAIR SPANS E & 1
CTDIICTIIDI	E No. 330162	<i>S17–08</i>	JOINT DETAILS	S20-01	GENERAL DRAWING	<i>S21–08</i>	JOINT DETAILS
S1KOC1 OK1 S16–01	GENERAL DRAWING	<i>S17–09</i>	JOINT DETAILS	S 20–02	TYPICAL SECTION	<i>S21–09</i>	JOINT DETAILS
\$16-02	TYPICAL SECTION	<i>S17–10</i>	BENT	S 20–03	DECK SURFACE REPAIR	S21–10	JOINT DETAILS
S16-03	DECK SURFACE REPAIR	STRUCTURE	E No 220110	<i>\$20–04</i>	JOINT DETAILS	S21–11	JOINT DETAILS
S16-04	DECK GORITICE REPAIR DECK UNDERSIDE REPAIR	S1KUC1UK1 S18-01	GENERAL DRAWING				
S16-05	JOINT DETAILS	\$18-02	TYPICAL SECTION				
510–0 5	JOINT BEITHES	\$18-03	DECK SURFACE REPAIR				
			DECK SURFACE REPAIR DECK UNDERSIDE REPAIR				
		S18-04 S18-05	JOINT DETAILS				
		\$18-06	END BENTS				
		\$18-07	BENT				
		51 0-07					
	STANDARD SHEETS						
		SD-1 TYPICAL CAP AND COLUMN REPAIR DETAILS					
		SD-2 DIAPHRAGM REPAIR DETAILS					

JACKING DETAILS

STANDARD NOTES





SD–3

SN

TYPE OF WORK:

BRIDGE PRESERVATION: DECK REPAIR, SILANE DECK TREATMENT, SILANE BARRIER RAIL TREATMENT, JOINT REPLACEMENT, BRIDGE JACKING, PAINTING EXISTING WEATHERING STEEL STRUCTURE, CLEANING AND PAINTING EXISTING BEARINGS WITH HRCSA, CLEAN AND EPOXY COAT EXISTING PRESTRESSED CONCRETE GIRDER ENDS, REMOVE DEBRIS FROM TOP OF EXISTING END BENT & BENT CAPS AND APPLY EPOXY COATING AND SUBSTRUCTURE REPAIR

Prepared in the Office of:

DIVISION OF HIGHWAYS
STRUCTURES MANAGEMENT UNIT

1000 BIRCH RIDGE DR. RALEIGH, N.C. 27610