

24238: Install truncated domes in sidewalk, approximately 15 LF from Gas station sign towards W. Rockspring St. Install domes to align with new ramp across W Rockspring St. Repair 6 panels of damaged sidewalk along radius.

24237: Modify for grass strip.



Curb Ramps To Be Repaired		
	Retrofit	
	Remove and Replace	
	New Curb Ramp	
	Remove Ramp	
	Municipal Boundary	
	NCHPO Historic Boundary (NR and LHD)	
2022 Vance		
WBS: 2021CPT.05.14.10911.1		
US 1 Bus		
From US 158 Bus To US 158		
	NORTH CAROLINA DEPARTMENT OF TRANSPORTATION DIVISION 5	
<small>Source: NV5 Engineers and Consultants Inc, ESRI, NC OneMap, NCDOT, NCHPO</small>		