

NOTES:

| | AS-BUILT REPAIR QUANTITY TABLE | | | | |
|-------------------|--------------------------------|------------|--------------|------------|--------------|
| HE | BENT 2 | QUANTITIES | | | |
| ON ER | | ESTIMATE | | ACTUAL | |
| L | SHOTCRETE REPAIRS | AREA SF | VOLUME CF | AREA SF | VOLUME CF |
| | CAP (VERTICAL FACE) | 31.8 | 15.9 | | |
| AILS'' | CAP (HORIZONTAL FACE) | 8.8 | 4.4 | | |
| - | COLUMN | 15.0 | 7.5 | | |
| THE | | | | | |
| OXY CTOR S. | CONCRETE REPAIRS | AREA SF | VOLUME CF | AREA SF | VOLUME CF |
| | CAP | 0.5 | 0.3 | | |
| | | | | | |
| | EPOXY RESIN INJECTION | LIN.FT. | | LIN.FT. | |
| | САР | 0.0 | | | |
| | COLUMN | 0.0 | | | |
| | | | | | |
| | EPOXY COATING | AREA SF | | AREA SF | |
| | TOP OF CAP | 156.8 | | | |
| | | | | | |