



<p><b>A</b></p> <p>FAYETTEVILLE ROAD SD-1 SEE TMP-2</p> <p>DETOUR M4-8 24"x12"</p> <p>← M6-1L 21"x15"</p>	<p><b>B</b></p> <p>FAYETTEVILLE ROAD SD-1 SEE TMP-2</p> <p>DETOUR M4-8 24"x12"</p> <p>↗ M6-2 21"x15"</p>	<p><b>E</b></p> <p>DETOUR M4-8 24"x12"</p> <p>EAST M3-2 24"x12"</p> <p>INTERSTATE 40</p> <p>← M6-1L 21"x15"</p>	<p><b>F</b></p> <p>DETOUR M4-8 24"x12"</p> <p>EAST M3-2 24"x12"</p> <p>INTERSTATE 40</p> <p>↑ M6-3 21"x15"</p>	<p><b>G</b></p> <p>DETOUR M4-8 24"x12"</p> <p>EAST M3-2 24"x12"</p> <p>INTERSTATE 40</p> <p>↗ M6-2 21"x15"</p>
<p><b>C</b></p> <p>FAYETTEVILLE ROAD SD-1 SEE TMP-2</p> <p>DETOUR M4-8 24"x12"</p> <p>↑ M6-3 21"x15"</p>	<p><b>D</b></p> <p>R11-2 (48" x 30") ROAD CLOSED</p> <p>W1-6L (48" x 24") TYPE III BARRICADE (SEE TMP-4)</p>	<p><b>H</b></p> <p>DETOUR M4-8 24"x12"</p> <p>WEST M3-4 24"x12"</p> <p>INTERSTATE 40</p> <p>← M6-1L 21"x15"</p>	<p><b>I</b></p> <p>DETOUR M4-8 24"x12"</p> <p>WEST M3-4 24"x12"</p> <p>INTERSTATE 40</p> <p>↑ M6-3 21"x15"</p>	<p><b>J</b></p> <p>DETOUR M4-8 24"x12"</p> <p>WEST M3-4 24"x12"</p> <p>INTERSTATE 40</p> <p>↗ M6-2 21"x15"</p>
<p><b>K</b></p> <p>END DETOUR M4-8a 24"x18"</p>				

6/8/2023 U:\Traffic\Transportation Management Plan\TCP\PLAN SHEETS\15BPR.124.3\_TMP\_04B\_310306\_FAYETTEVILLE\_RD\_DETOUR.dgn angood

<p>Stantec Consulting Services Inc. 801 Jones Franklin Road Suite 300 Raleigh, NC 27606 Tel. 919.851.6866 Fax. 919.851.7024 www.stantec.com License No. F-0672</p>	<p>DocuSigned by: Regina M. Muncy 43239 6/8/2023</p>	<p>DIVISION OF HIGHWAYS DEPARTMENT OF TRANSPORTATION WORK ZONE TRAFFIC CONTROL</p>	<p>BRIDGE 310306 PHASE I FAYETTEVILLE RD / I-40 DETOUR ROUTE</p>
--	--	--	--