

DRAWN BY :	BY : N.A. PIERCE				03/2022
CHECKED BY :		A.Y.GODFREY			10/2022
DESIGN ENGINEER	OF	RECORD:	N.A. PIERCE	DATE :	12/2022
					6/22/2023

+

+___

6/22/2023 R:\Structures\Plans\15BPR124\401_005_15BPR124_SMU_DSR01_S1-03_310306.dgn aygodfrey

PROVISION. REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE BASED ON THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ENTER THE ACTUAL QUANTITIES INTO THE DECK SURFACE REPAIR QUANTITY TABLE.

FOR SECTION B-B, SEE "EXPANSION JOINT SEAL REPAIR DETAILS" SHEET 1 OF 2.

DECK SURFACE REPAIR QUANTITY TABLE

SPAN A

	ESTIMATE	ACTUAL
CONCRETE DECK REPAIR	0.0 CU. FT	
SURFACE PREPARATION FOR CONCRETE BARRIER	754.2 SQ. FT.	
SILANE BARRIER RAIL TREATMENT	754.2 SQ. FT.	
SHOTBLASTING BRIDGE DECK	1424.6 SQ. YDS.	
SILANE DECK TREATMENT	1424.6 SQ. YDS.	
BRIDGE JOINT DEMOLITION	222.4 SQ. FT.	

APPROACH SLAB A

	ESTIMATE	ACTUAL
CONCRETE DECK REPAIR	0.0 CU. FT	
SURFACE PREPARATION FOR CONCRETE BARRIER	216.0 SQ. FT.	
SILANE BARRIER RAIL TREATMENT	216.0 SQ. FT.	
SHOTBLASTING BRIDGE DECK	426.0 SQ. YDS.	
SILANE DECK TREATMENT	426.0 SQ. YDS.	
BRIDGE JOINT DEMOLITION	286.2 SQ. FT.	

NOTES

DECK SURFACE REPAIR QUANTITIES REPRESENT ESTIMATED VALUES OF CLASS II SURFACE PREPARATION AND CONCRETE DECK REPAIR AFTER REMOVAL OF UNSOUND CONCRETE MIN. 2" CLEAR TO SAWCUT. SEE CONCRETE FOR DECK REPAIR SPECIAL

FOR SECTION A-A, SEE "FOAM JOINT SEALS FOR PRESERVATION DETAILS" SHEET.



SHOTCRETE REPAIR AREA



BRIDGE JOINT DEMOLITION

		CT NO. DURH E NO	AM		UNTY
SEAL OSTATS Prichola Prichola OSTATS Prichola		RTMENT	RALEIGH	NSPORTA REPAIF AND	2
		REVIS	IONS		SHEET NO.
DOCUMENT NOT CONSIDERED	NO. BY:		NO. BY:	DATE:	S1-03
FINAL UNLESS ALL	1		3		TOTAL SHEETS
SIGNATURES COMPLETED	2		4		15