

+

+

6/22/2023 R:\Structures\Plans\15BPR124\404_007_15BPR124_SMU_DSR02_S4-04_911084.dgn aygodfrey

DECK SURFACE REPAIR QUANTITY TABLE

SPAN B

	ESTIMATE	ACTUAL
CONCRETE DECK REPAIR FOR SILANE DECK TREATMENT	0.0 CU. FT	
CONCRETE REPAIR	0.0 CU.FT.	
BRIDGE JOINT DEMOLITION	0.0 SQ.FT.	
SHOTBLASTING BRIDGE DECK	1172.0 SQ. YDS.	
SILANE DECK TREATMENT	1172.0 SQ. YDS.	
SURFACE PREPARTAION FOR CONCRETE BARRIER RAIL	790.0 SQ.FT.	
SILANE BARRIER RAIL TREATMENT	790.0 SQ.FT.	

NOTES

DECK SURFACE REPAIR QUANTITIES REPRESENT ESTIMATED VALUES OF CLASS II SURFACE PREPARATION AND CONCRETE DECK REPAIR AFTER REMOVAL OF UNSOUND CONCRETE. (MIN. 2" CLEAR TO SAWCUT). SEE CONCRETE FOR DECK REPAIR SPECIAL PROVISION.

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE BASED ON THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ENTER THE ACTUAL QUANTITIES INTO THE REPAIR QUANTITY TABLE.



CONCRETE REPAIR AREA

		ECT NO. WAK GE NO.	Έ		OUNTY	
Z OSTATO SEASING Dy W SEASING D	STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH DECK SURFACE REPAIR SPAN B					
DOCUMENT NOT CONSIDERED	NO. BY:	DATE:	NO. BY:	DATE:	S4-04	
FINAL UNLESS ALL	1		3		TOTAL SHEETS	
SIGNATURES COMPLETED	2		4		21	