


PLAN - BOTTOM OF CAP

ELEVATION - SPAN D VIEW



AS-BUILT REPAIR QUANTITY TABLE QUANTITIES BENT 3 SPAN D FACE **ESTIMATE** ACTUAL AREA SF VOLUME AREA VOLUME SHOTCRETE REPAIRS CF CF 0.0 0.0 CAP COLUMN 0.0 0.0 LIN. FT. LIN. FT. **EPOXY RESIN INJECTION** CAP 0.0

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1" BEHIND REBAR AND MINIMUM OF 2" CLEARANCE TO SAWCUT. FOR REPAIR DETAILS, SEE ``TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

0.0

NOTES:


COLUMN

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE BASED ON THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ENTER THE ACTUAL QUANTITIES INTO THE AS-BUILT REPAIR QUANTITY TABLE.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.



SHOTCRETE REPAIR AREA



EPOXY RESIN INJECTION (ERI)

PROJECT NO. 15BPR.125.3

CHEROKEE COUNTY

BRIDGE NO. 190009

SHEET 2 OF 2

SEAL
031583

Docusigher PRASPONDING

Krishna P. Sedai

END VIEW

STATE OF NORTH CAROLINA

DEPARTMENT OF TRANSPORTATION

RALEIGH

BENT 3 SPAN D FACE

SHEET NO.

S1-21

TOTAL SHEETS 25

REVISIONS

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED 2

DRAWN BY: A. SORSENGINH DATE: 6/2022
CHECKED BY: S. AGUILA HERNANDEZ DATE: 6/2022