

AS-BUILT REPAIR QUANTITY TABLE QUANTITIES BENT 3 - SPAN C FACE **ESTIMATE** ACTUAL AREA VOLUME AREA VOLUME SHOTCRETE REPAIRS SF CF CAP 0 0 COLUMN 0 AREA SF VOLUME AREA SF VOLUME CONCRETE REPAIRS 0 0 COLUMN 0 0 LINEAR LINEAR **EPOXY RESIN INJECTION** FT CAP 0 0 COLUMN AREA AREA **EPOXY COATING** 87.0 TOP OF BENT CAP COLUMN

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1" BEHIND REBAR AND MIN. 2" CLEAR TO SAWCUT. SEE REPAIR DETAILS.

## **NOTES**

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN BASED ON THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ENTER THE ACTUAL QUANTITIES INTO THE REPAIR QUANTITY TABLE.

CLEAN AND REMOVE DEBRIS FROM THE TOP OF THE CAP AND APPLY EPOXY PROTECTIVE COATING. EPOXY COATING SHALL BE APPLIED TO THE TOP SURFACE OF THE CAP. THE CONTRACTOR SHALL NOT COAT THE AREA OF THE CAP BENEATH THE MASONRY PLATES. FOR EPOXY COATING, SEE SPECIAL PROVISIONS.

SHOTCRETE REPAIRS MAY BE REPLACED WITH CONCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

SHOTCRETE REPAIR AREA



CONCRETE REPAIR AREA

EPOXY RESIN INJECTION PROJECT NO. 15BPR.125.3 CHEROKEE \_ COUNTY

> 190010 BRIDGE NO. \_\_\_

SHEET 1 OF 2

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION

Krishna P. Sedai

—EA6F794150BF4B7... 09/15/2023

BENT 3 SPAN C FACE

SHEET NO REVISIONS S2-23 DATE: DATE: BY: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED TOTAL SHEETS 28

9/15/2023 S:\DPG3\15BPR.125.3\F1nal Plans\402\_045\_15BPR125\_3\_SMU\_B3C\_S23\_190010.dgn kseda1