ECONOLITE ASC/3-2070 EMERGENCY VEHICLE PREEMPT PROGRAMMING DETAIL

(program controller as shown)

1. From Main Menu select | 4. PREEMPTOR/TSP

2. From PREEMPTOR/TSP/SCP Submenu select | 1. PREEMPT PLAN 1-10

Place cursor in [] next to Preempt Plan and press 3. Then press the right cursor arrow and toggle the controller to YES. Next cursor down. This will select Emergency Vehicle Preempt #3.

PREEMPT PLAN [3] ENABLE....YES VEH/PED 1 2 3 4 5 6 7 8 9 0 1 2 3 4 5 6 OVERLAP A B C D E F G H I J K L M N O P ENABLE... YESIPMT OVRIDE.. IINTERLOCK. NO DET LOCK... XIDELAY.. OIINHIBIT... O OVERIDE FL. . IDURATION OICLR-GRN... NO TERM OLP. NOIPC>YEL YESITERM PH NO PED DARK.. NOITC RESRV NOIDWELL FL OFF LINK PMT...OIX FLCOLR REDIEXIT OPT. OFF X TMG PLN...OIRE-SERV.. OIFLT TYPE.HARD FREE DUR PMTIR1 NOIR2 NOIR3 NOIR4 NO --TIMING-----WALKIPED CLIMN GRI YELI RED ENTRANCE TM. 11 151 1125.5125.5 ----MIN GRIEXT GRIMX GRI YELI RED TRACK CLEAR 01 01 0125.5125.5 ----MIN DLIPMTEXTIMX TMI YELI RED DWL/CYC-EXIT 71 2.01 120125.5125.5 PMT ACTIVE OUT..ON PMT ACT DWELL...NO OTHER - PRI PMT.OFF NON-PRI PMT....OFF INH EXT TIME... 0.0 PED PR RETURN...OFF PRIORITY RETURN.OFF QUEUE DELAY.... OFF COND DELAY....OFF PHASES 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 PR RTN% 0 0 0 0 0 0 0

PROGRAM EXTEND TIME ON OPTICAL DETECTOR UNITS FOR 2.0 SEC.

ECONOLITE ASC/3-2070 OVERLAP PROGRAMMING DETAIL

(program controller as shown)

- 1. From Main Menu select 2. CONTROLLER
- 2. From CONTROLLER Submenu select | 2. VEHICLE OVERLAPS

OVERLAP A

Select TMG VEH OVLP [A] and 'OTHER/ECONOLITE'

TMG VEH OVLP[A]								TYPE: OTHER/ECONOLITE										
PH	HASE	ES	1	2	3	4	5	6	7	8	9	0	1	2	3	4	5	6
INCL	LUDE	ΞD	•	Χ	•	•	•	•	•	•	•	•	•	•	•	•	•	•
PRO	TEC	Γ	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•
PED	PR	ГС	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•
NOT	OVL	_P	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•
FLSH	H GF	RN	•	1	•	•	•	•	•	•	•	•	•	•	•	•	•	•
LAG	X F	РΗ	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•
LAG	2 F	РΗ	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•
LAG	GRN	۷ C).() \	ſΕL	_ ().() F	REC) ().() /	4 D <i>i</i>	/ (GRN	1 ().(

Toggle Twice

OVERLAP C

Select TMG VEH OVLP [C] and 'OTHER/ECONOLITE'

TMG VEH (DVL	Ρ.		[([[T١	/PE	: [)TH	HEF	R / E	ECC	ONC	DL	ΙTΕ	=
PHASES	1	2	3	4	5	6	7	8	9	0	1	2	3	4	5	6
INCLUDED	•	•	•	•	•	Χ	•	•	•	•	•	•	•	•	•	•
PROTECT	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•
PED PRTC	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•
NOT OVLP	•	•	•	•	•	•	•	•	•	•	•		•	•	•	•
FLSH GRN	•	•	•	•	•	1	•	•	•	•	•	•	•	•	•	•
LAG X PH	•	•		•	•	•	•	•	•	•			•	•	•	•
LAG 2 PH	•	•	•	•				•	•		•	•	•	•	•	
LAG GRN ().C) Y	ΈL	_ ().() F	RED) ().() /	ΔD,	/ (GRI	1 ().()

END PROGRAMMING

FLASHER CIRCUIT MODIFICATION DETAIL

IN ORDER TO ENSURE THAT SIGNALS FLASH CONCURRENTLY ON THE SAME APPROACH, MAKE THE FOLLOWING FLASHER CIRCUIT CHANGES:

- 1. ON REAR OF PDA REMOVE WIRE FROM TERM. T2-4 AND TERMINATE ON T2-2.
- 2. ON REAR OF PDA REMOVE WIRE FROM TERM. T2-5 AND TERMINATE ON T2-3.
- 3. REMOVE FLASHER UNIT 2.

THE CHANGES LISTED ABOVE TIES ALL PHASES AND OVERLAPS TO FLASHER UNIT 1.

ECONOLITE ASC/3-2070 PREEMPT FILTERING PROGRAMMING DETAIL

(program controller as shown)

- 1. From Main Menu select | 4. PREEMPTOR/TSP |
- 2. From PREEMPT/TSP/SCP Submenu select | 2. ENABLE PREEMPT FILTERING & TSP/SCP

ENABLE PREEMPT FILTERING & TSP/SCP FILTERED SOLID PULSING INPUT 1 ...BYPASSED.. ...BYPASSED.. 2 ...BYPASSED.. ...BYPASSED.. 3 .. PREEMPT 3. ... BYPASSED.. 4 .. PREEMPT 4. ... BYPASSED.. 5 .. PREEMPT 5. ... BYPASSED.. 6 .. PREEMPT 6. ... BYPASSED.. 7 ...BYPASSED.. ...BYPASSED.. 8 ...BYPASSED.. ...BYPASSED.. 9 ...BYPASSED.. ...BYPASSED.. 10 ...BYPASSED.. ...BYPASSED..

> THIS ELECTRICAL DETAIL IS FOR THE SIGNAL DESIGN: 12-1369 DESIGNED: MAY 2022 SEALED: 3/22/2023 REVISED: N/A

Final Design Electrical Detail - Sheet 2 of 2

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED



www.stantec.com License No. F-0672

Stantec Consulting Services Inc. 801 Jones Franklin Road-Suite 300 Raleigh, NC 27606 Tel. (919) 851-6866 Fax. (919) 851-7024



US 21 (Charlotte Highway) at SR 1100 (Brawley School Road) / SR 1117 (Wilson Avenue)

Division 12 Iredell County Mooresville PLAN DATE: May 2022 REVIEWED BY: E D Harris PREPARED BY: D A Waller REVIEWED BY: R M Muncey REVISIONS INIT. DATE

042678

750 N.Greenfield Pkwy,Garner,NC 27529

3/22/202 Derrick Waller SIG. INVENTORY NO. 12-1369