


## Strain Pole Attachments

## NOTE:

- 1. Strap all signal cables to the side of the pole with  $\sqrt[3]{4}$ " stainless steel straps when the distance between the spanwire attachment clamp and the weatherheads exceeds 3'-0''.
- 2. Provide minimum two spanwire pole clamps per pole.
- 3. It is prohibited to attach two span wires at one pole clamp.
- 4. For general requirements refer to NCDOT Standard Specifications for Roadway and Structures, January 2018.




chme

#4


**\_** 

Strai


10/11/2017 DATE



## Attachment of Cable to Intermediate Metal Pole



## Metal Pole Grounding Detail For Strain Pole and Mast Arm



NONE

S:\*IJS&SU\*IJS SIGNOIS\*SIGNOI DESIGN SECTION\*EOSTERN KEGION\*M SNEETS\*ZUIB\*ZU14 SIG.MB STO. FOBRICOTION DETGIIS≒STR rnzinser