

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION

ROY COOPER
GOVERNOR

JAMES H. TROGDON, III
SECRETARY

December 6, 2018

MEMORANDUM TO: John Williams, PE

Project Manager

RK&K — DocuSigned by:

FROM: Craig Haden

GeoEnvironmental Project Manager

Craig Haden

GeoEnvironmental Section Geotechnical Engineering Unit

TIP NO: I-5972 WBS: 44989.1.1 COUNTY: JOHNSTON

DIVISION 4

DESCRIPTION: I-95 at US 70 Business

SUBJECT: GeoEnvironmental Phase I Report

The GeoEnvironmental Section of the Geotechnical Engineering Unit performed a Phase I field investigation on December 5, 2018 for the above referenced project to identify geoenvironmental sites of concern. The purpose of this report is to document sites of concern within the project study area that are or may be contaminated. These sites of concern should be included in the environmental planning document in an effort to assist the project stakeholders in reducing or avoiding impacts to these sites. Sites of concern may include, but are not limited to, underground storage tank (UST) sites, dry cleaning facilities, hazardous waste sites, regulated landfills and unregulated dumpsites.

Findings

Six (6) sites of concern were identified within the proposed study area. We anticipate low monetary and scheduling impacts resulting from these sites. See the following table and figure for details.

Please note that discovery of additional sites not recorded by regulatory agencies and not reasonably discernible during the project reconnaissance may occur. The GeoEnvironmental Section should be notified immediately after discovery of such sites so their potential impact(s) may be assessed.

If there are questions regarding the geoenvironmental issues, please contact me, at (919) 707-6871.

cc:

Mailing Address: NC DEPARTMENT OF TRANSPORTATION GEOTECHNICAL ENGINEERING UNIT 1589 MAIL SERVICE CENTER RALEIGH, NC 27699-1589 Telephone: (919) 707-6850 Customer Service: 1-877-368-4968 Location: 1020 BIRCH RIDGE DRIVE RALEIGH, NC 27610

Website: www.ncdot.gov

GeoEnvironmental Phase I Report T.I.P.#: I-5972

Page 2 of 9

John Pilipchuk, LG, PE, State Geotechnical Engineer

Brian Hanks, PE, State Structures Engineer

Dale Burton, PE, PLS, State Locations and Surveys Engineer

Carl Barclay, PE, State Utilities Manager

Corey McLamb, PE, Division Construction Engineer

Matt Clarke, PE, Division Project Development Engineer

Lloyd Johnston, Division Right of Way Agent

Chris Kreider, PE, Geotechnical Regional Manager

Neil Roberson, LG, Regional Geological Engineer

Tracy Clark, ROW Unit, Negotiations, Asst. State Negotiator-East

row-notify@ncdot.gov

roadwaydesign@ncdot.gov

hydraulics_notify@ncdot.gov

(01) Property Name: Speedway # 6960

1669 E. Market St Smithfield, NC 27577

Facility ID: 00-0-000036566 Incident Type/Number: N/A **Property Owner:**

Wilcohess LLC 539 S. Main St Findlay, OH 45840

UST Owner:

Speedway LLC 500 Speedway Dr Enon, OH 45323



Anticipated Impacts: Low

This site currently operates as a convenience store/gas station. It is located on the northwest quadrant of E. Market St and Outlet Center Dr. According to the UST section registry there are three (3) USTs currently in use. No monitoring wells were observed during the site investigation.

(02) Property Name:

Sheetz # 511 1700 E. Market St Smithfield, NC 27577

Facility ID: 00-0-000038092 Incident Type/Number: N/A **Property Owner:**

PTM LP 5700 Sixth Ave Altoona, PA 16602

UST Owner:

Sheetz Inc 5700 Sixth Ave Altoona, PA 16602



Anticipated Impacts: Low

This Site Currently operates as a convenience store/gas station. It is located on the southeast quadrant of E. Market St (US 70 Bus) and Towne Centre Pl. According to the UST section registry there are four (4) USTs currently in use. No monitoring wells were observed during the site investigation.

(03) Property Name:

Panera Bread 1716 E. Market St Smithfield, NC 27577

Facility ID: 00-0-0000023565

Incident Type/Number: 23206, 42077

Property Owner:

Smith NC POOH, LLC 101 W 55th St New York, NY 10019

UST Owner:

Sunoco Inc

3801 West ChesterPike Newtown Square, PA 19073



Anticipated Impacts: Low

This site is currently a Panera Bread Restaurant, there is also an Arby's Restaurant on the adjoining parcel. It is the former location of Sunoco # 0614-3788. It is located on the southwest quadrant of E. Market St (US 70 Bus) and the I-95 south bound on Ramp. According to the UST section registry six (6) USTs were removed in August 2017. The site has since been redeveloped as the Panera Bread and Arby's restaurants. Incident #'s 23206 and 42077 are associated with the former facility (Incident #'s are for the same incident) and were closed out in 2002. No monitoring wells were observed during the site investigation

(04) Property Name:

Vacant Lot (B&S Texaco) SE Quadrant E. Market (US 70 Bus) and I-95 exit ramp Smithfield, NC 27577

Facility ID: 00-0-000030057 Incident Type/Number: 11797

Property Owner:

Old Brogden Farms II, LLC 6317 Bayswater Trl Raleigh, NC 27612

UST Owner:

Tommy Jarrett PO Drawer 8

Goldsboro, NC 27533



Anticipated Impacts: Low

This site is currently a vacant lot. It is located on the south side of E. Market St (US 70 Bus) at the I-95 north bound exit. It is the former location of B&S Texaco. According to the UST section registry six (6) USTs were removed in 1994. Incident # 11797 is associated with this facility and was closed out in 2012. The property was fenced off during the site investigation. One (1) abandoned monitoring well was observed on the outside of the fence on the service Rd.

(05) Property Name:

Trisha's Café 911 Mallard Rd Smithfield, NC 27577

Facility ID: 00-0-000014912 Incident Type/Number: 10973 **Property Owner:**

Mark Ryan PO Box 2458 Smithfield, NC 27577

UST Owner:

Fitchett Investments, Inc

PO Box 1407 Dunn, NC 28334



Anticipated Impacts: Low

This site appeared to be vacant at the time of the site investigation. It is located on the east side of Mallard Rd approximately 370 feet south of the I-95 exit. It is the former location of the Sun Towel Shop. According to the UST section registry four (4) USTs were removed in 1992. Incident # 10973 is associated with this facility and was closed out in 1993. No monitoring wells were observed during the site investigation.

(06) Property Name:

Village Motor Lodge 198 Mallard Rd Smithfield, NC 27577

Facility ID: 00-0-000029939 **Incident Type/Number:** 11409

Property Owner:

Danbar Limited Partnership PO Box 1333 Smithfield, NC 27577

UST Owner:

Village Motor Lodge 198 Mallard Rd Smithfield, NC 27577



Anticipated Impacts: Low

This site currently operates as the Village Motor Lodge. It is located on the west side of Mallard Rd at the I -95 exit. According to the UST section Two (2) USTs were removed in 1993. Incident # 11409 is associated with this facility and was closed out in 2006. One (1) monitoring well was observed behind the vacant restaurant. According to the incident database this well was installed in the UST basin and no contaminants were identified.

